1 6-30-68 cut deep cross in pavement #633604 (1)
4-1977 PK. nail in place in Blk Top over Concrete.

1/4 corner south 1/4 36 Marion 106-13.
North 1/4 1 Pleas. Grove 105-13.

7-1876 Hunter P301 no 296 L1 N. Neal.
found boulder stone set in ground avered by F Kinney that he and others set it in place of govt stake. (no mens).

4-1892 Thos Fraser P475 no 454 L 36. W Beach.
found boulder P301.
1/16 north set stone with cross on top - 6x6x20 M&L.
19.96 1/4 (this was star corner of Piedmont village

6-1903 Armstrong P63B L1 T. Donaldson.
found stone boulder 10x10x12 1' N of corner past over)

(also found 4x5x15 limestone S 40 10' E 7 1/2 lks from. Probably Nat'l Cor. Sec. Cor.
boulder) believed strongly to be true corner. Howeres used
boulder as corner as it was of record. Avers if ever
used again would destroy location of boulder as corner
a bearing tree suspect also points to limestone as
corner.
- west set 5x10x12 granite at fence corner on
town line and at 8.00 chains then a
- stone 1 1/4 x 12 x 14 at 20.00 chains as 1/16 corner.
- also 3x6x12 limestone at fence corner south 10.00
of stone that lies 8.00 west of N 1/4 1.

Gov't notes - Sept. 29, 1853 John Ball Dep. Surv.
West Between Secs. 1 & 36 33.00 ch. Brook 5 lks wide runs SW.
40.00 Set Post 1/4 Cor
Burr oak 9 N 76° E (bk)? 71 lks.
Our oak 12" S 35° W 134 lks.

See card #2.

#633604 (2)

Card # 2. S 1/4 36 Marion N 1/4 1 Pleasant.

6-30-69 J Kerr. corner deep under highway 52. 43.26 N. of ℄ RR ℄ Track ℄ RR ℄ Track
found 1/16 stone north, reset center 36 from true 1/4
corners east & west, N-S 1/4 line used 1/16 found and
corner set midway on north line 36 as in 1892.
- doubled distance from 1/16 to center 1316.42 R 1317.44
corner came in exact line fence south over pre-set
high way monument - cut deep erase in pave as corner
- corner in line fence south - 1.9' south center pavement.
- hole in top high mon sta 426+91.2 ℄ 48.35
Corner lies 70' W. of ℄ Road to North. - over.

- edge highway RW PoT post  NW 52.95
- punched cross center west end cattle pass type culvert in road north. NE 91.5
- Meas west to section corner. SW 36. 2636.3
- Meas east to Twsp cor mon. 2638.9
- ~~Cross~~ YA Corner in pavement as corner lies 4.2' north of E-W direct line 2606.8 north of C1M set as center of 1. of center 1 on direct line of now accepted E & W 1/4 corners. this measured 60. 2616.5 Taking mean meas of 2633.45' at E 1/4 north and 2591.2 at W 1/4 north. plus 4.2 that N 1/4 lies N. -/6 west set 1/2" x 3' rod. M & L at 13 18.22, corner in cluster of boulders and on tile cable line 2' deep, boulders old wire fence removed torn up by cable plowing. - corner lies 44.7' south of pav at 1/16 line. and. 102.0 ESE to center top tile standard ftt

S ¼ 36 Marion Pleas. Twnp (3)
#633604

1-12-76 Keith Ewens: corner 73' W of E road N.

7-1-81 1/16 West: Dug with backhoe and found condition to be poor. Someone had dug in a phone line and dumped boulders in. No trace of Armstrong stone to be found.

7-1-81 1/16 West: Dug with backhoe and found conditions to be poor. Someone had dug in a phone line and dumped boulders in. No trace of Armstrong's stone to be found.

7-1-81 20.37 chs. West of N¼ Cor.: Dug 486.75 West of 1/16 but found condition to be completely sand fill with no natural ground but gravel subsoil at ±3' deep.