Section Corner 1-2-11-12 Rochester 106-14

#640105

Check T.H. city survey

(1)

1961 Ken McGhie Found bolt in hole in pavement 25" North of Intersection
RP: M.H.D. R/W marker NE 46.50
Chisel + on NE side of State sign post NW 34.30

12-9-70 Co. Surveyor found round wood stake (3" diameter x about 2' long) under concrete pavt when the city of Rochester contractor had the sewer ditch opened up. - Sewer about 4' West of corner. - Top of stake about 1' below surface of concrete pavt. There is a horseshoe nail in the top of the stake which will be accepted as efort corner.
E.C. Bottler - Engineer on 3rd Ave SE paving, placed a corner in via casting 2.02' North of this stake and .08' West of said stake. (City Engr removed casting at this time.
K. McGhie placed a Chis'+' in pavt at .9' So. of N. edge

which was now torn out, this stake is .7' So of N edge of post which would be only .2' N of McGhie Replaced location. City Engr. inspector will place glass bottle in concrete paving over stake and we will place an iron stake later and take new references

4-12-72 RPs: SW corner of concrete block Mobil Station NE 82.30
NE Cor of Brick Dixon Cleaner Bldg NW 137.5
P.K. nail in ℄ 3rd Ave East N 97.0

11-29-77 Chipped through blacktop and found hole in concrete where bottle had been. Drove a RR spike in hole. Corner in ℄ of street North and 2.7 N of ℄ on the two West bound lanes of T.H. 14
RPs: Top center of fire hydrant NE 48.57
PK in centerline of 3rd Ave N 96.97
NE corner of Dixon NW 137.5
SW corner Mobil Station NE 82.36

#640105 (2)

Section Corner 1-2-11-12 Rochester 106-14

May, 1856 Thos. Hunter Pg. 7 No. 12 shows Sec. Corner 1/16 north 19.90 chs. then 9.95 chs. to 1/64 Cor then 9.95 chs. to 1/4 Post.

B.T.'s To 1/64 Cor. (N 79¼°E 138½ lks.) & (S 80¼°E 88 lks.)

7/6/84 Set a ¾" x 0.25' iron pin over RR spike R.P. Drill hole & Chisel "X" in Bore of 3 signal light

NW 48.57
SW 41.63
SE 48.42

Rochester section corner 1-2-11-12 # 640105 (3)

Govt Notes on Back

Gov't Notes W.B. Verby 1854

80.00 Set a corner post to section 1, 2, 11 & 12

Bur Oak 12 N 31¼° E ___ 1Ks
Bur Oak 12 S 52¼ E 228 1Ks
Made trench