X 7-21-76 CIM
4-3-78 CIM

#640404 #1

1/4 corner 4-9 Rock 106-14

10-1892 H Fraser P495 no 468 S3-4 Dorsey & Waldron
found remains of old stake in line of old fences
running south & east, set stone 2 x 5 x 12 in it's place.
-16 west stake M & L. 19.95
- Meas North from above 1/16 to inter E-W 1/4 line 39.66

12-1893 H Fraser P539 no 500 S9 Conflict, Stoppel.
found stone P495. no meas.

4-1897 H Fraser P606 no 551 SW 1/4 S4 Stoppel.
found stone P495.

Cover

-16 west set stake N & L 19.95
5-1926 C H D B 45 P 27. found 1/16 corner. west in place ??

12-1952 Mc Ghie.
1/2" rod over 3/4" pipe.

Sp	Power pole.	N	105.45.
℄	north end 24" Culvert	NE	31.4.
℄	south " " "	SE	30.0.
SE cor	stone machine shed	NW	276.9.

105.4 Ref Mon
1946 West Tie

Mar. 1969. 1/2" rod in place.
Co. Hwy Dept. Spike - Disc. in PP. N.E. 105.32
" " in Ore. to post N.W. 45.16

7-1-1974 Co. Hwy Dept.
Spk in disc in PP - N.E. 22.98
Spk in disc in PP - S.E. 113.2
Spk in disc in PP. W.N.W. 22.18

Also 2x2 Hub Transit Tie W. 29.8 West
Transition (on line To PP) = ℄ 107.40 west of Corner

#2

¼ Cor 4-9 Rochester 106-14
#640404

7-21-76 Dug with backhoe from CHD rod W. 4' and N. 6'. Found rod over another rod over J.K.'s 5' pipe 5' deep (removed all). Found W.O.F. 2" x 5" x 12" limestone 5' deep 4.83 N and .35' E of traverse point. Put rod on W. side of stone with stone and junk around. Set CIM over 5/8" x 20" rod over stone. Corner in ℄ N-S road and in line of power pole W.

R.P.'s CHD Disc N. side p.p. W 88.3
CHD Disc NE side pp. SE 116.63
CHD Disc NW side p.p. NE 86.10
Punch hole top S. end of 40" CMP E 57.19

4-3-78 Set 16" CIM over CIM in place. Checked R.A's O.K.
7/24/89 FD CIM FLUSH WITH C.R. # 122 IN ℄

Gen'l Notes W.B. Yerby Est Random 4-29

40.00 Set a temp sect. post

West between 4-9 bar 9'8'E

40.00 Set a section post in Mound of Earth and Set deposited charcoal Mark trench and pits plainly Osage Orange Stakes No 7

4-3-78 Set a 16" CIM over the CIM set in 1976. Checked all ties correct. Corner in the center of the N-S road.

7-1857 T. Hunter Pg. 34 No. 55 Shows 1/4 Post
Prop Cor. West 5.48 thence 16.85 to prop. cor. then 17.50 to Sec Cor.
Prop. Cor South 22.36 then 17.74 to Cen. Sec.
1/16 east 19.77 M&L (See Survey for Interior Breakdown)

1/4 COR 4-9 ROCHESTER 106-14 #640404 (3)

5-22-97 TIE OUT OF CORNER FOR CONSTRUCTION OF WCD. FOUND CIM IN GOOD CONDITION DOWN 4" IN BLACKTOP.

T@ FOX VALLEY

∠RT POND TO 1/4 COR 24°06'08" HOR 203.32

T@ POND

∠RT FOX VALLEY TO 1/4 COR 354°41'09" HOR 896.33

SET 1" SQ PIPE/CAP IN N EDGE OF RES. DRIVE EAST AS REF. PIPE.

9' N ℄ DRIVEWAY + 96' E ℄ CSAH #22

T@ REF. PIPE

∠RT FOX VALLEY TO 1/4 COR 239°49'56" HOR 100.33

7-15-98
TD-JJ-BB
#75

"640404" F

1/4 Cor. 4-9 Rochester 106-14

Drilled hole in Center of Center Left Turn Lane

C.S.D. in N. Side up 6.0' P.P. # Q4021 SE 116.50'

C.S.D. in N. Side up 5.0' P.P. # 09967 West 94.04'

C.S.D. in N. Side up 2.5' P.P. # 24093 East 101.45'

17.0' South & Down West

✓ Rochester Temp. "640404" G 9-10-98

Placed Brass Plug at 1/4 Corner of
4 South and 9 North