X 7/24/89 FD CONC. MON IN ROAD DITCH

(1) #640405

section corner 4-5-8-9 Rock 106-14.
5-1875 Hunter P272 no 270 S5 F Stoppel
Corner missing. Mr F. L. Stoppel owner he set corner
fence post in center of mound where old stake stood.
-16 North set stake M & L 19.90

10-1892 H Fraser P495 no 468 S3-4 Dorsey & Waldron.
Mr Stoppel had removed post & placed stone in place.
found evidence of old post so accepted stone as corner.
-16 east set stake M & L 19.95
= Meas north 39.81 1/2.

8-1893 H Fraser P527 no 492 S8 Stoppel (owner

found stone P 495
–16 west set stake & stone M & L. 20. 20.

4-1897 H Fraser P606 No 551 S 4 Stopple.
found stone set P 495.
–16 east set stake M & L 19.95
also found by Robt Fraser P664 4-1900 stone 2" above ground.
10-1952. Mc Ghie
Corner now 6"x6" concrete marker set in Mayo survey
by Williams in unrecorded survey.
– North corner conc footing — S W 137.2.
– top anchor bolt — S 43.65
— " " " — S E 65.6.
12-1975 corner 6"x6" Concrete mon. up 6" in S. ditch E-W blacktop road, 41' S of ℄ under E-W road Fence
RP CSD E side power pole NNW 7.80

Rochester Section corner 4-5-8-9 (L)

#640405

Gen'l Notes on Back

7-1857 T. Hunter Pg. 34 No. 54 Shows Sec. Corner
1/16 South 19.77 m&L
also Surveyed Sec. 9 North 1/2 at same time as Sec 8
on Pg. 34 No. 55
Prop. Cor. East 17.50 chs. Then 16.85 chs To Prop Cor. then 5.48 to ¼a.
See Survey for Interior Break Down.

Govt Notes W. B. Yerby (85?)

80.00 SE ¼ Post to 4, 5, 8+9 in Mound of Earth and Soil deposited charcoal Maple trench and pits planted Osage Orange N.W. - S.E. of trench