X 12-12-1975 CIM set #640505 (#1)

section corner 5-6-7-8 Rock 106-14

2-1897 H Fraser P605 No 550 & 8 J Burgwin
H Fabler.

found remains of old stake and identified stumps of all witness trees proving corner correct. set new stake with stone planted by its side.

took new B tree 6" burr oak. S 33½° W 25½ lks.

-16 south set stone and stake M&L 19.78½.

-16 east found stone M&L 19.98 & B tree.

- east drone stake at 6.00 chs then found stake & witness tree 15.50 chs east of NW 8.

(over)

1-1898 W Fraser P616 No 559 S5 Williams, Engle
— found corner P605 Coff.
— 16 North found stake set P1. drove new stake
& B tree 8" W oak S10°E 14½ lks. M & L. 19.97.
— also set stake M & L 9.98½ beto above 1/16 cor & SW5
Cor & east found corner P605 15.50 che east of
SW5 with slakes at 5.00 - 5.50 & 5.00 chs
24.46 on to S1/4 5.

Corner now 1¼" iron pipe no RPS.

11-1969 Sandstone pay 1/16 stone set P605 a limestone
to still in place South of section corner 5-6-7-8.

12-12-75 7 and 1¼" x 32" pipe driven down with shattered limestone in
5-6 E and W sides. Removed pipe and set CIM over ½" x 18" rod and
7-8 corner with pieces of limestone in N+S. set Corner 1' E of N-S
fence and 1' N of fence W and 1.5' NE of corner post.
RPS Spike + CSD W. side stand 10" Oak NNE 47.20 Spike + CSD W side mutilated 8" Twin Oak, E 46.0

#640505 (#2)

Section Corner 5-6-7-8 Rochester 106-14

1/16N of 5-6 / 7-8 Possible 1/16 Corner North of Sec Cor 5-6-7-8

12-19-1973 N Dug NW of corner post as indicated from Will Frasier bearing tree taken in 1897 and still standing. Found black mark in clay, which although did not go deep enough to determine if it was the stake hole, fit the bearing tree so closely we accepted it as corner. Will adjust if 1/4 Cor 5-6 found when possible to dig. Set 5/8" x 15" rod.

RP's: Nail S. side (Chokecherry?) tree SE 11.07
Nail E side Frasier Brg tree S 9.72
Corner 1' W of corner post to fence N-S-E and .62 S and at E of traverse nail

Bottle = 1' W (1986) Good wood Brace

Gov't Notes W.B. Year by 1854

80.00 Set a section post to 5, 6, 7 & 8
White Oak 12 N 60½ W 4 Lks
Cherry 10 N 4½ E 6 Lks
Bur Oak 18 S 57½ E 17 Lks
White Oak 547 W 13 Lks

April, 1856 Thos. Hunter Pg. 1 No. 2 Shows Sec. Cor.
1/16 North 20.13 chs. M&L Bearing Trees to 1/16 Cor.
(S 31 3/4 E 54 links) & (S 68° W 63 links).
meas. west 39.78 chs. to 1/4 post.

Aug. (1856) Thos Hunter Pg. 15 No 24 Shows Sec. Cor.
1/16. west 19.89 chs. M&L - 3 B.T.'s (N 18° E 11½ lks.) & (S 48° W 8 lks.)
(S 69° E 20 lks.)

Jan, 1858 T Fellows Pg 49 No 71 Sec Cor.
See Survey for S W. 1/4 Sec 5

Section Corner 56-7-8 Rochester 106-14 (3)
#640505
Dec. 1858 T. Hunter Pg. 58 No. 84 Shows sec Cor.
Meas. East Total of 39.93 chs. from 4 Prop. splits
Meas. North 40.26 chs. to 1/4 Post
(See survey for Interior breakdown of S.W 1/4 Sec. 5)

10-27-86, Sec. Cor 5-6-7-8: 7d CIM OK.
10-27-86, 1/16 N.: 7d 5/8" rod set 12-19-1975. Also
Found Pipe/plastic cap# 6507 .30E and .11 N.
W. Fraser Brg. tree now dead and lying on ground.
Rod checked OK to RP SE 11.07
2/22/90 Fd CIM set Sign/ post 1.0' east