X 10/28/96 SET 4' TELSPAR PIPE/C.I.C.

#640506 ①

1/4 corner 5-6 Roch. 106-14

1-1898 H Fraser P616 no 559 SW1/4 S5 H Williams. Engle Cobb.

Corner gone. run line SW 5 over 1/16 corner north & doubled distance which proved just 15.50 chs west of point set by Hunter - drove stake.

1/16 conch found stake set by Hunter & B tree stumps took new BT. 8" W oak S10°E 14½ lks. M&L 19.97.

- east set stakes at 5.00 chs, 10.50 chs and found stake at 15.50 chs east of W1/4 5

3-1902 H Fraser P36B S6 A Rose

(over)

found stake set as 1/4 corner P616
-16 west set stake M&L 19.70 3 Traylor 1990
-16 center SE 1/4 6 set stake M&L 19.97, E-W 1/16 line
-16 south found stake P616

Wrong Location.
corner now used 1" pipe under 1/2" rod origin unknown.
Sp 12" boulder SW 20.8 — Sp 8" oak stamp SE 19.5
set by McGhie ~~2 Rods westerly~~
Cor. 17.5' N. of fence but not midway or on line

6-24-74 Co. Surv. - found Bent 3/4" pipe Lying flat - Traced hole down about 18" - reset same pipe with Top about 12" in adj. field — Same hole Cor. now 16' N. of fence old post Stamp found North still inplace

---

10-14-1934 Archie Armstrong - Fd Bk 1 P. 24 says "Nothing here, dug a lot." - Found wood Stake 1633.2 west of Center Sec. 5 and set other Points on line west of Cen. 5

Rochester 1/4 corner 5-6 #640506 (E)

Cant Water on Book

11-1856 T. Hunter P 19 No. 31 NW. 1/4 sec. 5, N.E. 1/4 sec. 6 & S.W. 1/4 Sec. 32, 107-14

1/16 East 20.06 1/2 M&L - B.T.'s (N 54 3/4° W 66 1/2 lks.) (N 59° E 90 1/2 lks.)

1/16 west 19.70

1/16 North 20.00 Then 19.73 to No. 5-6

April, 1856 Thos. Hunter Shows 1/4 Post Pg. 1 # 2

1/16 west 19.70 chs. m&L

1/16 south 20.13 chs. m&L - Bearing Trees to 1/16 Cor (S 31 3/4° E 54 links) & (S 68° W 63 links).

Jan 1858 John Fellows Pg. 49 No 71 shows 1/4 Post
(See Survey for Land lots in S.W 1/4 Sec 5) (over)

Gen'l Notes W.B. Yerby 1854 North Random 5th 6

40.00 Set A temp. Sect. post

South between Sect 5th 6 course S 15' E

39.75 Set A Section post

Aspen 8 N 25 E 13 lks

Aspen 10 N 37½ W 26 lks

Dec. 1858 T. Hunter Pg. 58 No. 84 shows ¼ Post.
Meas. South 40.26 chs to Sec. Cor.
Meas. East 40.25 chs. with 4 Prop. splits Along the way

10/28/86 SET 4' TELSPAR WITH CLC AS CORNER AT DOUBLE THE LINE ; MEASURE FROM SEC COR 5-6-7-8 CIM OVER THE ½ N. (⅝" ROD SET 1975) CORNER AT N EDGE OF WOOD FENCE POST IN E-W FENCE, DROVE SURVEY MARKER SW ; POST .8 E OF CORNER.

#640506 (3)

1/4 CORNER 5-6 ROCH 106-14

10/24/80 SET PT @ DOUBLE THE LINE ; MEASURE OF SEC COR 5-6-78 OVER THE 1/16 N. POINT ON N. EDGE OF WOOD POST DUG 2'E', 1½'N, 1½'W ; 3' S. BY 3' DEEP FD NOTHING (SEE BACK OF CARD #2)

1/16 S OF 1/4 COR 5-6 FD 5/8" IRON SET 12-19-1975 ALSO FD PIPE/CAP 6507 .30 E & .11 N LARGE W. FRASER BRG. TREE, NOW DEAD & LYING ON THE GROUND CHECKED R.P. SE OK