X 10-8-68 set C/M pipe 5/8" x 7" rod. stone N side corner
9-23-77 CIM "correction of Corner" (1990) re-code survey

section corner west 7-18 Rochester 106-14. ①

east 12-13 Salem 106-15

#640705

12-1857 Hunter P40 no 62 Parts 1 & 2 106-15

" 6 & 7 106-14.

used corner. set 1/16 north M & L 19.81

BT - S 59° W 90 lks - found by armstrong 6-11-1903.

6-1886 Hunter P 413 no 402 S 7 Smith, Kunzemann found stub of old stake, set new stake with stones on east and west sides.

-1/16 north found NW B tree standing P40. found old stake driven in road.

(over)

staked school house grounds starting 22 chains east of mentioned 1/16 cor - then north of 1/16 line 2.5 chs E & W and 2.55 chs N & S.

3-1911 Chas Larson P148 B L7 Lewis Lake.
found boulder.
1/16 north found corner & stake N & L 19.90.
1/16 east found wood stake at 18.87 1/2. (1245.75

5-1912 Williams P168B L18. Kuskey, Bannon. Waldron.
found stone, monument set corners East from 1/16 cor L.
also replaced 1/16 east found with alive. (Cap W 4 18) (a stone)
1953 Mc Ghie found pointed boulder.
Sp PP SW 47.5 — Sp Tel pole NW 51.1 - Sp 12" oak NE 36.55
Co Hwy Dept 1945 - 553.3 west of Co road. 1553.3 ~~1~~ Lately
Gen dep lines for corner found no ties no corner. (blk 160)

#640705 (2)

Card #2 West 7-18 Roch 106-14
East 12-13 Salem 106-15

10-68 J Kerr found Stone and hub in natural soil
was digging previously too far north.
set C I M over 5/8" x 4' rod with piece of tile below
lower stone placed on north side mon, top mon down 10"
-30 D on west side dead red oak. NE 36.0
-30 D on SE side power pole # 8104 WSW 59.75
-point of angle corner post at top NW 65.35
- near center of traveled N-S road at that point.
- fence center south ditch of road west.
- average line of old fence running east 4' ± North ?

B140 P31 Co H D. found stone mon.
Meas east to Center transit line 1559.3

B159 P Co H D 1945 found stone mon
Meas east to 1/16 corner stone found 1241.6' R 1245.75'

-16 with iron rod in place.

12-24-1975 (1/16 E) Dug NE of corner post (fence E + W - fence S. gone). Found 2"x10" by 12" + (dug 12" in post) stone 1.35 W and .6 S of transit nail and 1.5' NE of post.

C.A. Prop. Cr. 10.92 ch N of W 7-18
9-21-77 Dug with back hoe. Found area cut. Found nothing.
9-22-77 Dug from ~~1/16th Rod~~ So found (believed to be Kastler)  by 4½' deep
Found nothing LRP } WNW 28.33 So 11.77

West 7-18 Rochester 106-14 (#3)
East 12-13 Salem 106-15
#640705

9-21-77 Dug 6'x6' NW of Kerr CIM. Found nothing
Dug again East and North of Kerr CIM. Found
two boulders standing side-by-side (E-W) Westerly
stone 4"x6"x9" and Easterly stone 5"x10"x11". Stones
1½' deep. Drove 5/8"x2' iron between the stones
where Hunter records setting a stake — did not
find stake. Corner 5.7N and 4.3 E of Kerr CIM.
9-23-77 Removed Kerr CIM and reset it over the
5/8"x2' iron set between the stones found.
Corner 3'N of fence East, 5'E of the center
of the N-S road and 15' So of ℄ of road
West.
RP's: Sp & CSD SW side 11" blazed Burr Oak NW 127.56

CSD E side pp stub NW 68.62

CSD N side pp # 8104 SW 65.74

Sp & CSD W side 15" Black Oak NNE 32.60

March, 1858 T. Hunter Pg. 50 No. 73 Shows Sec. Cor.
1/16 East 18.55 chs. then 20 chs. to 1/4 Post
B.T.'s to 1/16 East (S 81°W 49 lks) (S 40°E 107 lks)
1/16 South 19.78 chs. m&L to 1/4 Post
(See Survey for breakdown of N.W. 1/4 Sec 18.)

Govt Notes. Jn 67 1854
50.00 Set post ---. Sec. 12-13-7-18
Black Oak 6 N 60 W 13
Black Oak 5 S 75 W 10
Black Oak 6 S 88 E 73
Black Oak 8 N 67 E 57

5/2/89 SET REFERENCE
CI.C/P² AT PT BYRON
BANK, TURNED & LT
159° 30' 54" FROM
CAIRNBRAE TO W SEC COR.
7-18 DIS. 192.96

#640705 (4)

SECTION CORNER WEST 7,18 ROCH 106-14
EAST 12,13 SALEM 106-15

6/31/90 THE TRAVERSE TIE BYRON BANK WAS DESTROYED IN ROAD CONST., WE SET A NEW POINT BYRON BANK II USING CARINBRAE AND SMITH1 TO SET UP POSITION, TURNED NEW & TIE
~~TIE~~ BYRON BANK II, & RT CARINBRAE TO W 7,18
199° 54'00" 214.66'
BRUCE BELTER SET 5/8" IRON AT OUR LOCATION
ON 5/31/90 WE WILL FINALIZE AFTER
BITUMINOUS SURFACE IS LAID

11-02-93 Set 1"sq Pipe w/cap as corner in Blacktop CR #104
in ℄ CoRd #104 10½' So of ℄
R.P.'s
CSO in P.P. #52455 SW 70.69

Note: (Set out from Byron Bank II)