#1

5-9-1961 set C/M over steel rod. #640706
9-26-77 CIM Correction of Corner

1/4 corner west 1/4 4 Rochester 106-14.
east 1/4 12 Salem 106-15

12-1857 Hunter P40 No 62 Parts 1-12 106-15
" 6-7 106-14.

used corner. - set 1/16 north M & L 19.83.
- 1/16 west set M & L. 19.94.
- 1/16 south " " 19.81 BT S 59° W 90 lks.
(found BT 6-11-1903 armstrong)
- meas east. 38.06.

3-1911 Chas Larsen P 148 B S.T. Lewis Euke.
set boulder stone and stake.
1/16 south found corner M & L 19.90

(over)

- Meas east ~~39.90~~ 39.30? to center sec 7
- North found limestone at 19.90. - ~~[illegible]~~
(set by Huntley 1886 (p413) from stake set P40

Corner ~~found & used~~ set by MHL McGhie & others set iron rod.
5-9-61 J Kerr found iron rod set C/M over rod.
Sp twin oak NE 55.13
Sp tile pole NW 61.8.
no east-west roads. - lies center present road

1/16th So 9-20-77 Dug with backhoe and found 6"x8"x16" stone (dolomite) on So side of stake (removed stake to office) 1½' deep. Corner 2.05 N and 3.85 E of McGhie iron (removed) Replaced stake with a 2x2 hub and 1x2 hub and an iron bent over the stone
9-23-77 Set 5/8" x 18" rod ~~on~~ at the stake location

#640706 | #2

¼ Corner West ¼ 7 Rochester 106-14
East ¼ 12 Salem 106-15

1/16th N 9-20-77 Dug from pipe (removed) found on total line and used as traverse point 8' East, 6' North, and 2' So. by 1½' deep to clay. Condition poor. No black dirt on clay. Found nothing.

Charles Larson Prop. Corner 19 rds 22½ lks N of the W ¼ 7 9-20-77 Found 1½" x 20" iron 2' deep 1.75 N and 3.55 E of iron (removed) found at road surface possibly by McGhee. Set ½" x 12" iron @ surface over C.L. iron.

9-20-77 (West ¼ 7) Dug from a point 3' E of Kerr's CIM E 3' and N 6' by 9" deep into black dirt. Found nothing. Digging to cover C.L. meas. from property corner

found N and line from prop corner N to 1/16th So (found).

9-21-77 Dug again along East side of the monument Found a 10 x 10 x 22 boulder with a stake on the NW side 7' deep. Set a small angle iron in the stake hole. Set a 1¼" pipe on the West side of the boulder and a 5/8" rod on the East side. Stake 2.6E and 3.5N of CIM. and stone .3'E of stake. This corner CL's

9-26-77 Set a CIM over a 5/8" x 18" rod at double the line and measure of the 1/16th So - 1.8E and 4.3 So of C.L. stone and 4.4E + .8' So of Kelly's CIM (removed)

#6407069 #3

¼ Corner W¼ 7 Rochester 106-14

E ¼ 12 Salem 106-15

R.P.'s Punch hole top S. end CMP in field drive East ESE [redacted] 32.17

Punch hole top N end CMP in field drive East ENE 32.97

Old Disc in NW side twin Black Oak NE 51.00

Corner in center N-S road.

~~T.H. Perpet Corner 5.66 ch. W of the Center of SE¼~~ Sec.

T.H. School corner 22 ch. East of the ⅛th N of SW 7

9-27-77 Dug in the Centers of ~~E-W ROAD~~ at T.H. measure from the ⅛th West. Found nothing. Condition poor.

Geic Notes 7-67, 1954

40.00 Dist pool to point mk. ------

Bk-Ont 8 D 6 E323

Blk Ont 8 D 35 W 29

5/3/89 USED PT CHRISTENSON TURNED 2 RT 1/4 COR 1-12 SALEM TO W1/4 7 106-N 82° 11' 30" FOR DIST. 195.07'

7-2-93, Set 1" sq Pipe w/cap as corner in Blacktop CR # 104 In ℄ CR # 104 17½' North of ℄ Fielddrive East CSO in P.P. # 52445 SSE 130.75 (Note: Set out from Christenson)