X Conc. mons. inplace - 1975 #640805

section corner 7-8-17-18 Rock 106-14. ①
6-1900 Robt Fraser P 704 No 619 L 7 Burgoin
found stake anered by Burgoin as true corner after
some checking from existing fences. set new
burr oak stake with stone 2x7x15 by it. side
also drove iron rod beside stone. elm ac B tree
-16 North set stake N & L. 20.01 ½ which N 41 3/4° W
came near where Burgoin anered it would. He x 7 1/2 L
anera he will set stone by stake.
-16 west set stake with stone N & L. 20.07.
it came. abont 15' N W of bridge.

9-1911 Ch Larson P 148 B S7 H Christiansen.
found wood stake accepted as section corner SE 7.
- west shows S 1/4 7 at 20.00 entire mile 99.37 1/2

12-1960 J Kerr. found concrete Mayo marker.
1968 Sandstone. Found stone concrete mayo marker.

12-1975 Shot concrete Mayo Mon. on W. side
corner post to fences N-E.

Gov't Notes W. B. Yerbi 1854
80.00 set a section corner post to 7, 8, 17 & 18
Elm 12 N 75 W 18 lks
Elm 10 N 86 1/2 E 17 lks
Ash 9 S 44 1/2 E 30 lks
Ash 14 S 49 1/2 W 31 lks

#640805 (2)

Section Corner 7-8-17-18 Rochester 106-14

June, 1856 Thos. Hunter Pg. 9 No. 15 Shows Sec. Cor.

1/16 South 20.09 chs. m&L - B.T.'s (N 35 1/4° E 17 lks.) & (S 69 3/4° E 23 lks.)

1/16 East 19.42 chs. m&L - B.T.'s (N 35 1/4° E 66 1/2 lks) & (N 39 1/4° W 74 lks.)

Nov, 1857 T. Hunter Pg. 39 No. 61 Shows Sec. Cor

1/16 west 20.10 m&L to 1/4 Post.

1/16 south 19.92 m&L to 1/4 Post.

See survey for Interior breakdown of sec. 18

1981 McGhies concrete monument near old Fe int.

7/26/89 FD CONC MON. NEXT TO OLD POST, FENCE LYING ON THE GROUND. SET SIGN & POST ± 1.0' SOUTH