9-24-1963 set C/M with conc block on E side. (1)

#640905

section corner. 8-9-16-17 Rock 106-14.

12-1893 H Fraser P539 no 500 & 9 A Corpleth.

found stone as corner in earlier & Stoppel.

survey., then tested by 2 B tree stumps.

- meas east 40.13

Corner maintained with concrete building block.

with cross as riser to corner.

5-1926 C H D. B45 P25 found conc block - also

complete alignment of Mayhood road.

over

9-1963 J Kerr.

set C/M with building block on each side.

– center 4" steel corner post high

Mayo fence around private grounds

on north side trail road NNW 44.0

– 7" well casing. SW 18.05

3-7-77 (1/16th South) Found concrete Mayo monument lying on the ground. Dug but could not find the spot where it had stood.

3-14-77 Reset the Mayo monument M&L. Corner is on a sidehill 63' East of the center of a N-S ditch.

R.P.'s: Spike + CSD on W. side blazed 6" Elm N. 16.62

Spike + CSD SW side blazed 3" Elm S.E. 4.68

Rochester section corner 8-9-16-17 (2)

#640905

Corr Notes on Back

8/8/89 FD CIM SET SIGN & POST 1.0' SOUTH
15.0' NORTH TO ℄ OF DRIVEWAY

Gov't Notes W.B. 1/4 1854

80.00 Sec A post to Sec 8, 9, 16 & 17

Linn (Basswood) 12 N 27 1/4 W 22 lks
Aspen 18 N 38 E 28 lks
Linn (Basswood) 12 S 80 E 36 lks
White Oak 12 S 87 3/4 W 39 lks