7-18-1963. set CIM over stone & rod. #641104 (1)
T-3-86 dug hole with backhoe - removed @ 1m
¼ Corner 11-14 Rock 106-14
See also T. Hunter DK 4 p32-33 April 1875
12-1875 Hunter P289 No 285 S14 Williams, Alexander
found stake properly marked.
- Meas south 40.08 = 2645.28
- 16 west M&L 19.92½ = 1315.05 = 2630.1

4-1939 JKerr P442B S14. NE¼. LA Fellows.
found stone N¼ & NE cor 14.
- Meas east 1672.85 to S 63
then " 1060.8 to NE 14. Making 2733.65
check these meas.!
& 2732.60

6-1901 ~~Chas~~ Fraser P703 No 618 found stake & stones
Meas east 39.93 - 16 west 19.89 3/4 or 39.79½

7-1963. J Kerr limestone 1/2" riser.
set C I M over stone and rod.

Disc	power pole	S	28.0
"	" "	NNE	27.1
Spike	16" oak	N	40.7
60 D	24" boulder	NW	58.37

1930 C.H.D. Book # 65 page 30 - Iron Pipe

Ties	Nail in 12" oak	North	40.7
	Nail in Box Elder	N.W.	58.4
	Nail in Cor Fence post	S.E.	34.9

Measure S.W. Cor. 12 to ℄ T.H. 63 (1062.5)

#641104 Card #2

¼ Corner 11 - 14 Rochester 106 - 14

April 1875 T. Hunter field Book 4 p. 32-33 Sec. 11 - Toogood at "F" = S. ¼ Cor. 11 found stump of NE B.T. and also But-cut of Tree lying on ground, by cutting into stump found marks and on cutting into log found (¼ S) on said log. Took Bearing and Dist. from Stump S? N? 47° E 255 lks To old stake stg. Standing. The SW B.T could not be found and no Traces of where tree stood could be found. found stones around old ¼ post and roots of old poles in ground around stake and on testing its position ran from "E" (SW. 11) the Section Corner To old stake at "F" and found it To correspond very closely with Bearing of old line run by me in 1855 and also found old Blazed Trees on the line and was satisfied that the old ¼ post as just found by us stands where it was originally set and that there is an error in the field notes as to the distance from B.T. found To said stake. Set new Br'd stake properly. Marked & set old stake by its side and also buried broken stones around Bottom of stake - Meas West 39.87 =

July 6 1855 T. Hunter field Book 13 p. 6+18 Sec. 11-106-14
Variation of E-W line Thru Center Sec 11-106-14
Jones N. line 8°33', Jones S. line Bears S81°W.
dist. 39.87.

Page 18 S.W.¼ Sec. 11 Comm. at the N.W. Cor. of said S.W.¼ Jan 26 1856

July 6, 1855 T. Hunter field Bk 13 p 9 Sec. 14 Geo. Walfords
This survey comprises the N.E.¼ of N.W.¼ Sec. 14, commencing at the ¼ Stake on N. Side of said Sec. and Running West

(1) S 81°W 19.93½ (2) S 9°35'E 20.04
(3) N 81°E 19.93½ (4) N 9°35'W 20.04

Gov't Notes W.B. Verby 1854 East Random 11-14
40.00 Set temp. Sec post
West between 11-14 course 9°04'E
39.95 Set a section post
Bur Oak 12 N 17 E 210 lks
Aspen 9 S 45½ W 246 lks

#641104 Card #3

1/4 Corner 11-14 Rochester 106-14

3/31/86 FD CIM, HEAD GONE, IN RD. CHECKED OLD RP'S OLD DISC IN W SIDE OF P.P. SO. 28.07
OLD DISC IN E. SIDE PP. NNE 27.08
SPIKE IN S SIDE BOX ELDER NW 58.37
DIDN'T FIND SPIKE IN OAK, DROVE PK. IN CRACK IN NEW CONCRETE CURB ON W SIDE OF 5TH AVE SW RUNNING SO (PK 10.04 SE OF FIRE HYD.) PK TRANSIT TIE, PK TO CIM 66.19 & RT 137° 17' 33" TO VERT. RAILING POST ON TOP OF WATER TANK SOUTH (1ST ONE EAST OF CENTER OF TANK)

7/3/86 DUG WITH BACKHOE FD CIM OVER 5/8" ROD, OVER WAGON WHEEL HUB, OVER OLD CLUTCH MECHANISM, BUT NOT ~~STAKE~~ FD WITH STONES AROUND & 1"X4"X16" LIMESTONE ONE SIDE STAKE 1/16 W OF 1/4 COR 11-14 ROCH. NORTH OF 20TH ST & 1.8' CIM

4/1/86 FD 1/2" RE-ROD 7 1/2 N E

1/4 COR 11, 14 106-14 11/10/88 FOUND 5/8" PIPE CHECKED TIES, TIES GOOD, CHECKED PK NAIL TRANSIT TIE. ACCEPTED 5/8" PIPE AS CORNER

6-13-97 - FOUND 5/8" PIPE IN GOOD CONDITION. 1' N ℄ 20TH ST SW
31' E ℄ 5TH AVE SW.