X 3/28/89 SET 5' TELSPAR PIPE W/ CIC IN PLACE OF CIM
~~12-14-71 set CIM on 1/4 x 1/2 Non rod~~ - #641404 (1)

10-6-1978 Co. Surv. dug hole 3' dia. 2½' deep - 7'-10" So. 5'-8" E. of above CIM

1/4 Corner 14-23 Rock 106-14

5-18 7.4 Hunter P250 no 251 S23-24. J Easton after running line M & L found B tree H & D Smith. then found old stake remains exactly one link east of M & L. - east 39.68 1309.77 on line.
-16 west set stake M & L 19.84½ or 39.69
-16 south set stake M & L 19.93
-16 center NW 1/4 23 set stake at inter line of N-S 1/16 line and 1/16 line over to 1/16 cor on east section line south of NE 23. line north rough & brush.

12-1895 Hunter P 289 No 285 & 14. Williams delander.
found stake set P250.
-16 north set stake M & L. 19.97½.
-16 west found stake M & L. 19.84½. P250
- meas east 39.68

---

iron shaft as corner many years.
property line & corners set west from corner. 669.2'
corner now in direct area new 52 by pass. may or may not be last.
1/16 west a pipe at edge woods SW & brush NW with southtown Subdiv. SE pipe lies 3'± west & 4'± south of cor post. rags on fence opposite rod. or pipe. this set accurately on section line - very brushy west.

Card #2. 1/4 14-23 Rochester 106-14. #641404 (2)

12-14-71. Co surv. re locating corner destroyed in grading of highway 52 by-pass

- found 2 lot corners on dead end street - projected and meas line west 417.85 from westerly edge of street lot corner.
- cont meas west to property corner set by JKer 668.92 R 669.2
- found 1/16 pipe corner between 1/4 14-23 and 14-15-22-23 projected line from 1/16 corner over property corner which came about .5' north of nail set.
- projected line from C/M at center 23 over 1/16 corner, a 1¼" pipe = (5' west and on line of L side small grain utility shed.) this pipe set when corner was in place also found 5/8" rod on exact line under E-W fence on crest about 400'± south of 1/4 corner. this line came less than .1' east of line & meas nail (over set.

set CIM over 3/4" x 3' rod. at point relocated.
RP. 25.5 S.S.W. to N edge concrete SE bound lane where
form crack comes to edge near aiming at corner.
89.86 ESE to single punch mark in center N end
3' Galv stud culv flare apron
corner lies off N edge SE bnd lane in line old fence
running west westerly of service drive 4'± south of fence W.
1/16 west still in place as recorded 3'± west of fence S.
Coor Notes W. B. Hr. b/ 1854 East Random 11-23
1/0.00 set temp Sec. post. West between 11-23
course 9° 03' E
39.9 1/2 set section post
Bur Oak 15 to 3c 11/1 E 125 lks
Blackoak - S 133/4° W 111 lks

#641404 (3)

Oct. 1978 RWB

¼ Cor. 14-23 Roch 106-14

After considerable research and analyzing the current measurements in Sections 14 and 23, I concluded that the CIM inplace at this ¼ corner should remain where placed To avoid disturbance in all the Subdivided areas especially North into Section 14.

However, I believe the original Gov't ¼ Corner location is about 8' So. and 6' East of the present CIM location. On Oct. 4, 1978 I, alone, dug a hole in The T.H. 52 inslope of the E. B.L. of the Hwy To see if a chance of the remains of the stake and stone set by

W. Fraser in , could still be found. I checked with Mn/Dot on the original field x-sections of that immediate area and found the spot to be cut several feet as per their grading plans. I dug a hole 3' dia. 2½' deep to original soil (below 2' of fill) No chance of finding anything. I, earlier, had found the 1/16 Corner Stone (a L.S. appx. 2"x8" Top) South of this ¼ Cor. Set by W. Fraser, Stone is ±5' So. and ±2.6' East of a 1¼" pipe set by Kerr and used as 1/16 Cor. for plats of Southtown & S.T. Heights. This would move ¼ 14-23 about 10' So. & 5.2' E of C.I.m. — T. Hunter in 1874 said ¼ Cor. (from B.T.'s) was 1 link East of midway and line. M & L, Today, places ¼ Cor. 6'± East & 7'± So. of C.I.M. ¼ lines from South, places ¼ Cor. 6.7' E. and 10'± So. using Qtr23.

See card # 4

#641404 (4)

1/4 14-23 Rock Twp 106-14

On Oct. 4, 1978, I dug for the 1/16 Corner N. of 1/4 14-23 and found a small boulder ±(5"x9"x10") about 4' So. & 3.5' E. of a 1/2" pipe which is used, I presume, as the 1/16 cor. (I also "probed" a stone just So. side of 1/2" pipe which could be J. Kerr's Stone which he set in 1948 (BK39 p. 72). Stone boulder as found did not have appearance of being set for very long although it was setting upright and Top 8" deep because dirt around it was silted-in and it appeared Too high up, I removed stone and dug down another 12" but did not find stake as set by W. Fraser. found Telephone service line cables about 15" deep almost under Stone boulder but probably just on N. side of boulder as it did look disturbed. (over)

I did not investigate this area very thoroughly. Also located a 1¼" pipe (up 12") in E-W fence about 17' East of ½" pipe, probably Lot Corner for lots To South.

Dropped further investigation at this time but we should probably dig for 1/16 Corners both E and W of ¼ Cor. Marks before a final conclusion or acceptance is made.

R.W.B. Oct. 6, 1978

Govt Notes on Mon 2

3/28/89 FD CIM ON DITCH SLOPE OF TH 52 LEANING NORTH BADLY, DUG OUT MONUMENT AND SET A 5' LONG TELSPAR PIPE / CIC OVER 3/4" X 36" IRON THAT WAS BENEATH THE CIM. THE 1971 TIE TO THE CONCRETE SLAB WAS 25.5' AS IT IS NOW.

1/4 14.23 ROCH