X 10-21-68 C I M set over 1/2" x 2' rod driven into orig stake hole found. Orig stone by its side. 8-1970 pulled C I M ~ took R.P.S. (1)
6-13-79 Reset C.I. over orig stake & 1/2" rod

1/4 Corner 19-30 Rochester 106-14.

#641904

extend table

6-1859 Hunter P61 No 89 S. 30.

used corner for lines south.

-16 south corner N & L 19.81 (1307.46

-16 Center NW 1/4 30 corner 19.80 from N - 20.00 from E.

6-1889. Thos Fraser P433 No 420 L19 B Clark, etal.

Corner gone, No B bees, no evidence or knowledge of corner

- Meas south line sec 19 78.43 (5176.38'
- set boulder 10x16x16 on section line at perp. meas.
- east 39.86 1/4 (2630.93' west 38.56 3/4 (2545.45'

7" white oak N 18 1/2° W 78 1/2 Lks. 51.81 (over

4-1923 J Kerr (Kerr Field BK-8 p.6)
Corner gone found N.W.B.T. set stone with cross
4x14x18 at 52' from 18" W oak N 17°30' W
New B tree 10" br oak N 89°30 E 74.8'
- set stone as center 2636.6 north with 1/10 stone north of
center N&L 1319.7 - center stone 2x9x18 over stake on E
side corner post

10-1962 Co H Dept found large boulder set 2x2 hub.

10-1968 J Kerr found county stone and hub, didn't believe
corner as found as it didn't check either line or meas.
- dug with tractor south and west
- found very old large pasture stake and witness stone
7.1' south and 4.5' west of county corner see Card #2.

#641904 (2)

1/4 19-30 Rochester 106-14. Card # 2

1968. Meas east ¼ corner found 2630.62 R 2631.25

Meas west " " 2552.55 R 2545.5

-this meas to C/M at W 19-30 as set 10-21-68 on direct line from north intersection line SE 19 over S ¼ 19.

-2 hub SW 19 36.6 from fence west R 33' and 3' east & N-S road.

- pushing corner west would increase meas as left SW 19 as set.

RPs- corner in line west edge traveled road surface south.

- corner lies 4' west of fence north.
- corner lies 9' south center east-west road.
- disc power pole #25258 SE 46.4 Gone 1974
- pipe line marker pipe 1974 ENE ~~ESE~~ 188.4
- ½" pipe 8" south of corner past NNE 33.0'

(over)

Cross cut in east headwall Gone 1974 ~~SE 29.3~~

" " " west " Gone 1974 ~~SW 18.6~~

8-1970 3/8" x 3' rod driven under fence
north up. 4" driven to bed rock N 95.0

10-1968 set C I M over 1/2" rod in slate hole by stone.

8-1970 removed C I M set 1/2" rod as temp
corner during grading

19.74

Dug down to 1/2" rod E of stone - reset
C.I.M (extend #ble) over the rod

R.P.s

Punch hole W End 24" C.M.P. SW 27.67

C.H.D Disc E side R.P.# 92070 SE 52.53

Note. Removed 1/2" pipe set by McChie & B. Corner Now .05 N + .05 W of their pipe

Rochester 1/4 corner 19-30 #641904 (3)

Govt Notes on Back

7/11/89 DUG WITH JACKHAMMER FD CIM IN GOOD COND.

Gov't Notes W.B. Yorkey 1854 W. Ransom 19-3-

Set a temp stone. post

East between Sect. 19+30 Course N 89° 58' E

38.70 Set a stone post

Bur Oak 8 N 5° E 4-1 Ks

Bur Oak 8 S 39° E 29 1 Ks