1 10-11-68 set C/M over orig stone & iron rod. (1)
#641906

1/4 corner. West 1/4 19 Rochester 106-14.
East 1/4 24 Salem 106-15

5-1872 Hunter P200 No 209 S 24 H Mc Cullough.
found short stake center road below surface.
used only to set center section 24

6-1874 Hunter P255 No 255 S 24. Holdt, Anderson.
found short stake center road P200.

4-1898 H Fraser P624 No 566 S 24. K. Larson
E Erickson.
found stone in center road. set in 1894 in survey
replacing stake P255. No mens.
stone lies in line fences east and west.

4-1923 J Kerr P 390 B S 19 C W Mayo.
found stone - drove iron rod thru old slab between 2 stones
- meas east 2566' to center 19 set ascorner
- meas north 2640.85 to NW 19.
- 1/16 center NW 1/4 19 set stone - 1326.4 E to 1/16
1320.27 N to 1/16

10-68 found stone with tractor, set C/M over rod.
Meas north very close to above record 1/6 Feet in place.

- disc in old cedar corner post	east	52.2
- disc in new cedar gate post	WNW	33.8
- center large maple tree (lone tree)	WNW	33' ±
- corner lies 2.0' west center traveled road (1968)		

Nov. 1857 T. Hunter Pg. 39 No. 61 shows 1/4 Post
Meas. East 38.92 to Center Sec. 19.

1/4 ----- West 1/4 19 Redmon- 10 E-14 #641906 (2)
East 1/4 24 S.Lem 10E-15

Govt Meas. Y. by 1854

No. of Dec post & from elevated stake.
to geod. ----. Bears ----/
with limb. Plated S.E. Orig.
N.E. Mark Scribe.

7/17/89 FD CIM DOWN IN GRAVEL ROAD IN GOOD COND.

7-19-96 CHD TIED OUT CORNER FOR CR 104 GRADING. SET 1" SQ PIPE/W CAP+ SIGN 74' WEST OF CORNER.

TIE REF PIPE
ART NE COR EDGE GREY SHED (NOT OVERHANG) SE TO W 1/4 COR.
314° 01' 28" HOR 74.325 REMOVED CIM

(641906) D

12-1-98
MW EA

85

W 1/4 19 106-14 Rochester
E 1/4 24 106-15 Salem
Set 120d spike in Crushed rock CR #104 as Corner from 1996 Corner Reference Tie. The Corner falls in ℄ N-S CR # 104 and 10' South of Fence line West and in line of Fence East.
Ref pipe w/Cap WNW 74.33'