#642005

9-24-1963 set CIM over orig stone (1)
6-13-74 Reset CIM over former CIM in place
section corner 19-20-29-30 Rock 106-14.
5-1877 Hunter P314 No 308 $29 J Lee, B Clark & others
found stake in center road, stated N W B+ proved correct.
- meas east 40.11 1/4 (2647.4'
- meas south 39.68 1/2 (2619.2'
- 16 center NW 1/4 29 set marked stake intersines.

6-1889 2hoc Fraser P433 No 420 $19 B Clark & others
found old stake remains with 5 x 24 x 24 stone
claimed by settlers as preserved as site of orig corner.
- set new stake and replaced stone on top.
- meas west 39.86 1/4 (2631.25' to stone set then
38.56 3/4 (2545.5 to " town line (Orig

4-1923 J Kerr. P 390 "B" CH Mayo L19.
found stone dug. set pointed red boulder on tap with +.
- mear north 2625.4 to Fraser corner which
proved to be M & W.

9-1963 J Kerr used corner many surveys.
set CIM. over corner stone to preserve corner.
- 5/8" rod. at fence corner North 36.88.
- 120 D on south side enormus
Cottonwood tree WNW 124.0.

10-1968. J Kerr - mear west to 1/4 corner
found after extensive digging. 2630.62 R 2631.25
then 2552.55 to SW 19.0 R 2545.5

#642005

Card # 2 19-20-29-30 Rochester 106-14 (2)

11-28-73 Catch up data missed recording in elaborate road re grading survey made in 8-20-1970 and ± date did not pull C/M and did 1/4 19-30 C/M for grading.

Knew RP to massive cottonwood W N W 124.0 would be lost new RPs.

75.0 N to 3/8" x 4' rod up 4" under fence north

165.8 E S E to 20 D N side 12" elm in edge yard.

Note 59.5± above tree north to approx section line between sections 20 and 29.

above notes were in scrap notes and were not recorded at time of re-grading

over (1974 R.P.s)

Punch hole E. end 24" field drive C.M.P. N. ~~30.26~~ 6

C.S.D. E. side gate cor. post N.N. ~~44.02~~ ~~42~~ 2'

14.1

3/8 x 4' rod (up 4") under fence North N. 75.0'

Gov't Notes W.B. Yr. by 1854

[redacted]

80.00 SC' A Cor. post to section 19, 20, 29-30

Bur Oak 17 N 82 W 29.1 lks

Bur Oak 70 N 18 E 32.1 lks

trench

7/11/89 DUG WITH JACKHAMMER FD C.M. WITH GOOD COND.