9- ~~1963 set C/M in place of pipe~~ Removed C.M. - Aug.-'74
accepted Me+B rod - 9.38' so. of above. C.M.

¼ corner Center 26 Rock 106-14 #642609

4-1890 Thos Fraser. P438 No 425 S 26 Baker, Taney Convey.

set stake ~~at witness line~~ But did not drive it at inter. Dues.

-16 south set boulder 8x8x16 M&L 19.98½

Corner used by Minn Hwy Dept & surveyors in place for many years

9-1963 Ikes pulled ¾" pipe, really solid.

set C/M down some as corner lies in field.

6' north of E-W fence about 200' west of west RW of U.S. 63 - should be better referenced, likely dog over on fence S.

Kerr apparently made error in running E-W 1/4 line as McGhie set iron on E-W 1/4 line which is 9.38' So. of Kerr's C.I.M. — after Traverse run around Sec. 26 by us, it proved McGhie Corner To be only a few tenths from Correct location according To our Computed location. Decided To accept McGhie Iron as Center of Sec. 26. (removed Kerr's Castiron, but left whatever was below mons.
Corner now ± 3' So. of E-W fence and ± 200' west of T. H. 63.

Oct, 1857 T. Hunter Pg. 38 No. 60 Shows Center Sec.
Meas. West 39.77 chs. to 1/4 Post.
Meas. East 39.53 chs. to 1/4 Post.
1/16 south 19.76 chs. M&L to 1/4 Post.

October, 1989 Crow Fd 3/4" rein inside cent rein sewer pipe shot rein from T.H.63 and it computes to probably be McGhie Iron.