1 8-7-72 set C/M ores ~~Hunt 24' [illegible] m~~ gunfield
8-17-1974 reset monument 5/8" rod 2622.82 M&L ~~[illegible]~~
1/4 corner 27-34 Rock 106-14 (1)
#642704

5-1875 Hunter P274 No 272 S 27-34 J M Talbert.
no corner, in swamp, witness fictious notes as no trees ever grew anywhere near or any corner ever set.
- Meas & run line carefully. Hunter on chain,
set marked stake M & L. 39.76½ 2624.49
-16 west set temp stake M & L 19.88¼ (1312.575)
-16 east set marked stake M & L 19.88¼
-16 north set " " " 19.98½.
-16 center ¼E¼ 27 set stake M & L 19.88 on E-W ¼ line
-16 center ¼W¼ 27 " " " unless lines (on creek bank)
-16 center NW¼ 34 found fence corner set on unless lines
-16 south set stake M & L 19.98¼.
-16 center NE¼ 34 M & L 19.97 on N-S ¼ line

1882 Capton

6-1903 Ch Armstrong P64B L 27-34 Talbert, J. Carr.
on swamp. could find no corner. set temp point
for line north M & L. 39.80 = 2626.8.
-16 east found Hunters stake. which was OK on
mens but 6" south of direct line of section corners.

8-4-72 ran electronic traverse from 27-28-33-34
to 26-27-34-35 - mean 5245.64 ½ 2622.82'
R Hunter 2625.15 Armstrong 2626.8 JKer Comp ~~2622~~
- 8-7-72 dug for 1/16 west of 26-27-34-35 and found
large boulder. 30" ± x 16" ± x 16" ± very pointed with point up.
about 1.3' S of computed line and near exact ¼ distance
between section corners 2312.41 set heavy axle with
flare lug on end 1¼" to 1½" x 28" on exact section line
and 1/16 distance above. .3' too far west until
an if corrected.

see Card #2

Card # 2. 1/4 27-34 Rochester 106-14 (2)
#642704

Cent line and electronic meas west and set.
1/4 27-34 in ~~open cultivated field~~ Golf Course at 262282 RH 2625.15
- set C/M. below ~~two inch pipe~~ set 5/8 rod with cap below monument.
- there is a deep drainage ditch running E & E ly.
some 50 or 60 feet in southerly direction from corner.
241.6 S E ly to 40 D on S side blazed huge cottonwood
in clump of several trunks - westerly in row of trees.
402.75 N NW ly to 20 D on E side large 24"+ lone redoak.
may use corner over C/M at Center 34 for line to S 1/4 34.

- over Correction note. -

12-22-1972
Due to slight angle error in traverse computation
Measure of section line 5246.84 Corrected to 5245.64
so 1/4 corner as set ~~must move 6 0 East~~ moved July 17, 1974
1/16 corner left as is (could go East .3'
Measurements given are corrected data
Govt Notes W. B. Yerby 1854 EAST Random 27+31
40.00 Set temp post in Marsh
West Between 27-34 8° 27' E
39.84 point for post in Marsh
48.00 Set Sec. Cor
B. OAK 10 N 1/2 W 36 IKs
B. OAK 6 S 66 W 77 IKs

10-17-75 Fd CTM OK, 34 1/2' SW'ly of small willow at edge of Fairway