7-11-1961. set CIM in rock of small boulder.

#642706

1/4 corner 27-28 Rock 106-14.

5-1875 Hunter P274 No 272 S 27-34 TM Talbert found part of orig lying on ground, also piece of old stake in ground covered by D Ryan as orig corner. - set new marked stake in its place.

-16 east set stake N&L 19.89.

-16 south " " " 19.98 3/4.

-16 center SW 1/4 27 set stake inters lines. comes on south bank of creek, near edge of creek.

6-1903 Ch Armstrong P64B. S 27 part of 34 H Talbot found stone like inverted kettle with peculiar groove on N Side. under fence running east put mark on top & stake beside stone. -16 east set stone 10X14X16 N&L 19.80 ones - J Carr. 1306.8

flat topped boulder in cluster of small boulders used for years as corner, brass in center stone.

7-1961 set C/M in place boulder. small stones set around corner.

-16 east 1309.0 to boulder with 1/2" pipe below at fence corner as 1/16 corner. R 1306.8 to boulder. 10x14x16.

-16 south 1317.87 to pipe in center road as 1/16 corner. set M&L in 1956? pipe near center road in line fence north. - also rod property corner M&L 658.93 North.

-1/4 corner lies under fence running east, 3.3' E of fence N.

Gov't Notes W.B. Yerby 1854 FENCE N-S NOW IN LINE, C.P. 0.3' SW. 5' BOULDER 2.0' SE

40.09 Set A section post in Mound of Earth and Soc / depos'd Charcoal / Mark trench and pits

Plan'd Osage Orange Seed E&W at trench

1/4 CORNER 27-28 ROCH 106-14 (2)

10/3/89 FD CIM, 2.0' SE TO LARGE 5 FT WIDE BOULDER, 0.3' SW TO NEWER CORNER POST TO FENCES N-S-W #642706

10/6/89 1/16 E OF 1/4 27-28 FD 1 3/4" PIPE ABOVE GROUND BENT, OVER 1/2" PIPE DOWN 1.5' ON EDGE OF PLOWED FIELD, FD ROCKS & BROKEN GLASS AROUND PIPES, 1/2" PIPE ALSO BENT, STRAIGHTENED AS BEST WE COULD, SET FIBERGLASS POST 1.0' SOUTH RP.

2.44' EAST TO PLASTIC DISC IN CORNER POST TO FENCE SOUTH