X 6-1-79 Set C.I.M. #643204 #1

1/4 corner south 1/4 32 Rock 106-14.
north 1/4 5 Ht Forest 105-14.

5-1874 Hunter P 252 no 252 L 32 J.P. Dibble.
Corner missing. searched carfully & extensively.
set stake midway (no mear) and in line fence
east (now road) as fence angled set exactly
on line when corner stood. came center N-S road.
-16 north set triangular stone boulder. 7 x 10 x 20
M & L 20.06. 1324.0 To center 32 a boulder 6x7x14.

Co Hwy Dept set Conc ~~Monu~~ monument with
B 272 P 4. 6-1960
3/4" iron riser (now center black top road. owner.
Meas south 5272.16 North 5292.88

1964 J Kerr used corner to find section corner west. (N W corner 5)

Meas east to C/M. ~~2644.5~~ 2636.14 after changing S.E. 82 ?

" west to C/M set 2644.0

RPs N¼ 5 center (once disc) 18" maple. NW 83.5

Disc power pole. SW 59.6.

" tele pole. NE 55.2

" fence post SE 90.38.

~~10-1941 Kerr BK 26 P.36 fd corner in Road - set 3/4" pipe~~

1936 BK 81 P.47 Co. Hwy Dept.

Found Ptd. Boulder

R.P.'s S.E. Corner of House - N 63°30' W - 151.0

24" Cottonwood - N 32° W - 75.9

Clump Willows N 80° E — 193.0

Gate Post — S.W.— 55.9

Meas. So. 5272.1 — Meas N. 5289.9 ?

1/4 Corner South 1/4 32 Rochester #643204 (#2) 106-14

North 1/4 5 High Point 105-14

5-23-77 Dug at CHO rod. Found rod over 23" concrete monument (cut to 4" x 4" top and 5" x 5" bottom) over a 2" x 2" hub over a 6" x 7" x 12" boulder lying flat 5' deep (boulder 1' into clay). Removed all.

5-24-77 Dug again farther West and North. Found nothing. Diggings now:



Set nail back at County location and referenced.

R.P.: CHO disc on So side pp # 9891 SW 59.46

Punch hole top N end CMP to road West NW 37.0±

SE corner of house NW 150.1

corner in ℄ road N-S-E-W

1/16th N

5-23-77 Dug from t.n. set in ℄ and in line with fences E and W 2'W, 3½'E, 2' So, and 5' N. Old road on clay 4' deep. Found 8"x12" mark in clay 1.7 W and 1.6 N of t.n

6-1-1979 Found ½"x11" (with twist) iron in new blacktop which fit R.P.'s taken 5-24-77. Removed iron and set a CIM on a ½"x18" pipe at the corner. Corner in 2 roads N-S-E-W.

Additional RP's:

Punch mark in lug on top S. end 18" C.M.P. in road East SE 37.60

Punch mark in lug on top N. end 18" C.M.P. in road East NE 37.71.

1/4 corner - South 1/4 32 Radius - no iron (3)
North 1/4 5 No Evidence found
Govt Mon in Knoll 1954 #643204
40.00 Set pipe & guard stake
Bk in D 37 E 25 C
Bk in D 16 W 27 C
10/5/89 FD CIM IN BLACK TOP CHECKED RP's (1979) TIES CHECKED GOOD
59.32' (59.46, 1979) SW TO CHD DISC IN PP# 9891

6-28-96 FOUND CIM IN GOOD CONDITION. SET REF PIPE W/CAP ON EAST EDGE OF FIELD DRIVE SE OF COR ____ SOUTH OF ℄ CR# 148
T@ REF PIPE
4RT PK NAIL IN PP# 24934 (2nd POLE WEST OF CORNER ON SOUTH SIDE TWP RD)
TO SOUTH 1/4 32 26° 23' 20" TO S 1/4 32 HOR 76.46

7-3-96 REMOVED CIM

10-25-96 CHD SET 1" SQ PIPE W/CAP.