1 5-14-1964 set C/M over ½"x 2' rod, by line & mean.
#643205 (1)

section corner. south 31-32 Rock 106-14
North 5-6 Hi Forest 105-14
5-1874 Hunter P252 No 252. S32 J. P. Dibble.
found remains of old stake in center road and
fected stump by S.W. B tree with marks plain
corner correct as found, likely left as found.
-16 N set Marked stake M & L 20,00 (1320.0
to ¼ 31-32 (a stake found near fence corner.

6-1879 Hunter P315 No 309 S31 J. P. Dibble.
found stake described P252.
-16 W set stake M & L 19,82 (1308.12 S ¼ 31 in river.
-16 N found stake set P~~252~~

Over

5-1964 I Kell dug twice over large area carefully and found nothing, run line from accepted 1/4 31-32 south. over 1/16 property corner fence east close to 2640 with fence east at 1320 (may have set 1202 by corner post at 1320. Meas from east. S 32-33 (later set 8.36 west. 1.44 north. 2644 each 1/2. Set CIM over 1/2" x 2' rod on placed corner.

40.5 SE to dice in power pole.
32.5 N to pipe 1½' S of corner post
80.1 S to 40 D on small twin oak.

Card #2 South 31-32 Rochester 106-14 (2)
North 5-6 Ht Forest 105-14 #643205

7-28-72 dug with tractor (mainly on information of Armstrong survey which had marked 105-14 but finally identified as 105-13, without any doubt, stapled) dug all sides of C/M (as yet not found 1/4 32-33 (8-4-72) and reset S 32-33 8'+ west)

(1) found vertical small knotty stake in clay 1½"x 10" about 2.2' south - 6.8 W of C/M very unlikely corner
20.5 WNW to top of steel post
27.4 N to Ht of Hedge row (not good RP
6.5 NE dust to C/M

(2) found 5" rotted cedar post some 5' S of C/M not formed, a rotted barb fence post stub (over)
32.2 NW to same post 29.25 N to Ht of hedge

accepted Kerr's Corner until more evidence proves it wrong. RE

Govt Notes. Kennedy, 1854

80.00 Oak post corner to section 5-C-31-32

Brook 10 N 44 E 127

" " 10 N 2 W 131

" " 14 S " W 74

" " 12 S 70 E 2.8

101284 FD CIM RP'S

40.57' SE TO CSD IN PP# 44 272

80 66 SOUTH TO 40d IN TWIN OAK

32.5' NORTH TO PIPE

CORNER POST NOW GONE