/ 4/24/75 SET 3/4" ROD #643206 #①

1/4 corner 31-32. Rock 106-14.

5-1874 Hunter P 252 no 252 d 32 J Dibble.

found old stake after digging by old fence corner.
then found & identified stumps witness trees.
drove short stake even with surface.
-16 south. set marked stake M & L 20.00
- staked 1/16 line east for fencing.

6-1877 Hunter P 315 no 309 d 31. J Dibble.

found stake P252 tested stumps B trees.
-16 south found stake P252 M & L 20.00
-16 center LE 1/4 31 set stake inters lines
-16 west. set marked stake M & L 19.95.

1964 J Kerr. - looked for evidence of corner, could not identify anything positive - run line south to locate NW cor sec 5 10S-14. Checked meas of 1/16 fence east - set corner at NW 5 by this line & line from east. Nothing positive about any part of NW 5 could still be there Could definately set or check if run in from south - E 1/4 6. Record 1/4 31-32 south 20.00 M&L
line run proned fence line east very close.

~~8-272. Taped N-S section line.~~ ?

Gov't notes. July 1854 Wm Verby, Dept Surv.
40.00 ch. Set Qr. Sec. Post
BTs Br oak 12" N 52° W 142 lks
Br. oak 12" S 56° E 71 lks.

4-24-75 Set 3/4" rod at double the measure of corner post at 1/16 south (1319.0) and on comp. line between Sec. Corners (R.P.'s) on Next card)

#643206

1/4 Cor. 31-32 Rochester 106-14 #(2)

(4-24-75 cont.)

R.P.'s: Spike and disc SW side 10" Oak NW 9.73'
Spike and disc NW side most northerly of twin Oak (8") NE 8.37'
Spike and disc on E. side 7" Oak N. 27.54'
Disc on N. side 12" brace post SE 20.87'
Corner lies 7.1' North of east-west fence.

10/3/89 FD 3/4" TLOD IN GOOD COND.

Gen'l Notes W.B. Yerby 1854

40.00 Set a Section post

Bur Oak 12 N 52 W 142 LKS

Bur Oak 12 S 56 E 71 LKS

10-25-89 SET WITNESS POST / SIGN IN FE LINE S