12-12-1961 set CIM over orig boulder. #643405 (1)
section corner south 33-34 Rock 106-14.
11/3/96 set CIM over CIM
1992 NE, BC 5/8" pipe over CIM North 3-4 Hi Forest 105-14
5-1875 Hunter P 274 No 272 S 27-34 J M Talbert
found mound in perfect shape stake missing.
6-1882 Caption - set 16 east marked stake MTL 19.94½
(1316.37'
-16 center SW ¼ 34. set stake
MTL on N-S 1/16 line. 19.98½.

7-1903 Book 10 unrecorded (also pg 713 No 6205) S 3 Higgins-Talbert B10P17.
found boulder stone coming to a point which R Fraser.
Shanrahans claim as correct corner Meas E 5296.5

10-1911 Ch Larsen P 162B S 3-4-9-10 P Shanrahan over

found boulder as corner.
Meas south 40.30 to boulder as corner.
typical Larson, no details, no explanations etc.

12-12-61. J Kerr with help of REA men.
dug extensively found large green pointed boulder.
also found assumed mc Glue pipe 5' away.
did not record.
Placed CIM over boulder
Transit ties to corner.

1½" pipe	N	60.0	O.K. Nov. 1974 on transit line
bridge bolt 1' east 30" oak	S	65.6	— gone in Nov. 1974

Code Nov. 1954
30.00 Set post to meet to corn. 5-4-55-34
Built mound with stone. Post chained 5' E.
Plowed S.E. Corner ours, N.E. Corner ours.

#643405 CARD # 2

SECTION CORNER SOUTH 33-34 ROCH 106-14
NORTH 3-4 HIGH FOREST 105-14

11/3/86 FD 16" 5/8" RE-ROD SET OVER CIM BY CHD 6/24/86, DUG DOWN TO CIM. FD HEAD GONE. BROKE BOTTOM SECTION OFF OF 16" CIM AND SET TOP PORTION OVER MONUMENT IN PLACE. CORNER, 1 FT. SO. OF ℄ RD ; IN LINE WITH FENCE SOUTH. CHD DISC IN W. SIDE PP# 9814 S. 36.79 CHD DISC IN NE SIDE PP# 44269 NW 72.95 PIPE N. 59.94