#643605 (1)

X section corner south 35-36 Rock 106-14.
north 1-2 Hi Forest 105-14.
2-1872 Hunter P193 no 204 S2 Thos Carroll.
Peter McCluskey.

corner gone, but corner post of field fences on west side of road. owned by James Purcell (his SE corner of field) to be on exact line west and 30 feet from post stake as it stood in mound.
- south 39.29 to corner set then 39.66 to SE cor 2 see P294.

5-1876 Hunter P294 no 289. S2 Thos Carroll, E Mountain corner used in correct tie in to relocated 1/4 cor 1-2.
now south 40.07 then 38.88 to SE cor 2.

Co Hwy dept 6 1958 1-1969 Not County

1/2" iron in blacktop NE 44.4.

spud in power pole 70.0

" " tele " W 43.15

" " fence cornerpost.

1974 Co. Surveyor dug with backhoe over large area, did not find anything, will used rod as found

---

See T. Hunter Book 5 p.79 6-1878 Sec. 35

7-74 R.P.S Spud NW side pp #9913 NE 44.49

Spud tele pole NW 70.04

CSD W. side tele pole SW 80.15

3' West of C.R. #20

Set a Round headed bolt back at the location of the rod that was in place

Section Corner found 35-3C Rodman 10C-111 (2
Nail 1-2 N. Fence 10S-14
Govt Mon. found 1954 #643605
80.00 Set post & drive wood stake for
corner & scribed 1-2-35-3C. Built mound
with stones. Placed S.F. Orig.
Orig. Sets N.E. Mon. & Stone.

9/89 FD BOLT DOWN 10", 3' WEST OF ℄ C.R. #20,
CHECKED TIES, TEL POLE SW GONE
TEL POLE NW CUT OFF, NW 70.05'
SPUD IN PP# 9913 NE 44.50