9-9-1961 set C/M. over stone Pkg nail. dup 18" E

#650104 ①

1/4 Corner 1-12 Salem 106-15

2-1882 Hunter P375 No 366 S/ P. & J. Hinde.
Corner gone. - Meas 40 chains west of SE cor. 1
a stone found. to subdivide north.
- east set temp point no line 16.69 from SE cor 1.

4-1902 Armstrong P34B S/ J Mannanniac.
found stake on section line but not midway in
line fence. running south. (plat shows stone) found later
- Meas east 40.15 2649.9
- 1/16 west set 3X10X12 limestone M & L 19.96 ± 1317.56
(over)

1/16 north set stake M & L. 19.84 (1309.4)

9-1961 J Kerr. B84 P21 Hennessey.
found stone set C/M
- meas east 2648.86 - west 2635.4
- 1/16 north set 1/2" x 4' rod. M & L 1308.2.
- In searching for SW cor 1- 9-1965 found S 1/4 1 to be .9' north of direct line orig stones and in line fence south.
5.0 north of center E-W road. now quite deep due to additional road surface additions 18" ±
Sp. 18" burr oak NNW 68.5 - center 26" oak NE 144.5'
(corner should be raised up) - also set 1/16 rod west (see SW cor 1).

North 6-16-70
marked corner only 10" deep
set 3/4" x 42" rod with alloy funke emith 100.0' - 5/8" C/M and
Checked to see if 1/16 cor west still on

#650104 (2)

1/4 Corner 1-12 Salem 106-15

Set by Michael Karnick 6-1854

18.00 Creek 8 lks wide runs NE.

20.00 Same creek SE.

20.75 Over bend of same SE.

40.00 Set quarter section post in mound with trench pits charred stake and Osage orange Seeds NE & SW

Dec 1851 T Hunter Dy 4C NO ec Stone 1/4 Post

1/16 No. th 19.75 chs Mtl to Centre. Sec

1/16 East 19.97 chs. Mtl to Sec Co.

(See Survey Fc. Interior breakdown).