1979 Correction of [illegible] from wood stake found.
9-6-1961 set C I M
7-2-79 - Rec'd cor. at inter. sighting lines 3 3/4" x 15" p.pe ①

Center 1 Salem 106-15.
#650109

1/4 corner

4-1902 Armstrong P34B S1 J. Mannannian.
set stake at true inters lines
this came. in line fence west and 1' east corner post.
-1/16 south. set stake M & L 19.84. (1309.4).
-1/16 west " " " 19.99. (1319.34).

9-1961 J Kerr B84 P21 S1. Hennessey.
found stake set C I M.
corner came 1.5 east and .5 south of corner post
N-S-W fences (over)

1/16 south set 1/2" x 4' rod M & L. 1308.2'
- Meas north to ℄ pavement 2618.7

6-11-70 Co Surv. only meas of record 1319.34.
Meas C1M at Cattle guard to 40 D by gate post (1'SE) in exact line of fence N 1325.25 then 1316.0 to 120 D set 1965 at 2640 from C1M now 2641.25, this 120 6' west ℄ traveled road.
1/2" rod set on direct aerial line directly east of pipe line guard corner nearer center road. see 1/4 1-2.
RP Center • 7' North - 1.4' east of Mon line fence west & south
bird nail on E side brace post south 8.53
" " " N " " " west 8.97

7-2-1974
Reset this cor. at intersecting lines by obs. traverse comp.
Set a 3/4" x 18" pipe down 12" as the cor. Removed 3 Barb
o.z. on RP's Nail E. side 6" cedar cor post South. 11.18
Cor. falls 1.7' West of the line of the fence running South.

1/4 Corner Center 1 Salem 106-15 (2)

Dec. 1857 T. Hunter Pg. 40 No. 62 Shows Cent. sec.
#650109

Meas. East 40.00 chs. to 1/4 Post.

1/16 South 19.75 chs M & L to 1/4 Post.