6-2-1965 set C/M over 5/8 x 18" rod. (1)
#650306

1/4 corner 3-4 Salem 106-15.

7-1873 Hunter P 233 no 235 L 4 Fairbanks, Strain Jacobson.
found short slab on west side corner
post claimed by Mr 21st Waite as orig corner.

10-1921 Chas Larson P 362B L4 4 Waite.
found hard head boulder
-1/16 south set limestone 5 x 9 x 12 M & L. 20.00
-1/16 north. set concrete slab 7 x 12 x 20 gont prop.
20.00 chen 19.43 1281.38. to NE cor 4.
this corner came 28 lks north of present E-W 1/16 fence
evidently set Midway.

over)

1/16 west set temp point to use in subdivide south
M & L 19.86 1/2 (1311.1')

6-2-1965 J Kerr
dug extensively found nothing by corner past 3 way fence.
1/16 south found recorded stone also section corner.
run & meas line using these corners found to be
1318.7 from 1/16 south to section corner placed C/M.
over 5/8 x 18" rod at this point. Later after setting NE corner
section 4 by doubling over NW 4 & N 1/4 4 moved the C/M.
less than one foot east to be on section line.
Corner corner 1' ± just north E-W fence in line fence
south. corner post has nub nailed to it.

#050300 (2)

1/4 Corner 3-4 Salem 106-15

Set by Michael Karrick 6-1854

S13 W on true line between Sections 3 & 4

39.43 Set quarter section post in mound with trench, pits, charred stake and Osage Orange seeds NE & SW

6/12/90 FD CIM LEANING BADLY SE'LY. DUG DOWN TO 5/8" ROD SET UNDER CIM BY J. KERR 1965. RESET CIM OVER ROD. NAILED SURVEY SIGN ON NORTH FACE OF C.P. TO FENCE E-W. S FACE OF C.P. SOUTH 1.7'