/ 7-11-68 set C/M above orig stone with ½"x10" rod + glass below stone

#650506

1/4 Corner 5-6- Salem 10 6-15 (1)

6-1870 Perry P 126 no 159 S 6 for Cook.
Corner gone, B trees gone set marked oak stake
on sec line 40 chs north of SE cor sec 6.
an oak stake standing Tested by B trees.
- Meas east line Sec 6 79.33
- North 1/16 at 19.82½ and 19.50½.
- Meas south 20.00 and 20.00.

4-1894 H Fraser P 545 no 505 S ½ S 6 Foudt Isaacson.
found stone planted as corner, left as is.

over)

1/16 south drove stake M & L 20.00.

5-1966. B 92 P 49. J Kerr.
Run line W 1/4 6 over 1/16 corner east past center not found to area of E 1/4 6. chainage favorable likely stable. dug area about corner past which area must be very close to direct E-W 1/4 line found nothing did not have probes. set rough stake in dug up area just south of corner past. Not authentic corner.

7-9-68 J Kerr found stone easily with probes boulder 6 x 8 x 14 with limestone under neath flat like a plate for stone above. Stone 2½' east and 1½' north rough stake above. Meas south to stone found 7-10 2637.8 with fence running east at 1319.0 set 2" stake on south & east sides. also glass and ½" x 20" rod 100' north unmarked.
7-11-68 set C I M - lowered stone with ½" x 10" rod below - steel post 6' north

(2)

#650506

1/4 Corner 5-6 Salem 106-15

Set by Michael Karrick 6-1854
39.68 Set quarter section post
Burr Oak 12 N 24E 4/5
Dug trench

7-22-1980 (1980 Remon Book) 1/4 Cor 5-6: Found Kerr's CIM 4.00 East & .06 South of traverse nail by corner post
RP's: Spike in corner post West 5.04
The corner is 3' East of the line of the fence North and in line of fence West