#650806 (1)

X 9-28-70 located corner
Set 1/4 Cor
1980

X 1/4 Corner 7-8 Salem 106-15

5-1893 W Fraser p 508 no 477 S 18 Laverte Chuckan, Isaacson

found stone set by Hunter in unrecorded survey. no mention what section Hunter was working in Likely Sec 7 as stone was found at center 7 with no record - used this stone to set section corner 7-8-17-18 by mean from SE cor 18 to above stone short 66 lks per 1/2 mile or 2636.04 set SE cor 7 at that mean and on a prop mean from NE cor 17 to NW cor 18 short 35 lks per 1/2 mile with 1261.0 as westerly 80 rods or 2634.2 - no sign of stone or where it lay as to center road etc.

Over

10-1930 J Kerr found Center T B3 P30 notes say set boulder rocks and glass but verbal record claims corner found nearly on N edge road. 1970 line came on stone with N-S aerial C1M .26 too far east taking east edge stone.

8-28-70 Meas from C1M set as T-8-17-18 in 11-11-1969.
North - found fence east at 1322.7 - set nail at 2644.0 which came at eyeball center of road west - set ⁘ on E & W ends diagonal cuts for ties to all points set later
RP to 2644 nail NW 33.9 - NE 20.19 road slopes sharply up to west - gradually up north

9-16 70 ran exact E-W 1/4 line from W 1/4 T found 9-4-70 and 9/16 east and Center found 9-16-70 - set 5/8" x 12" rod on pullback some 200 west of area of 1/4 T-8 to the exact line
RP small rod pipe cap in PP# 8619 due south 27.8
rod came very near center road as graded

see card # 2

Card # 2 1/4 7-8 Salem 106-15 #650806 (2)

9-16 To punched line To PK nail on east edge road at 1/4 7-8.
RP NW 44.2 to ⊙ W end 18" culv. 18.38 N to ⊙ E end 18" culv
this line came 3.82 south of 2644 or 2640.18 from C/M.
which will be moved 3.84 north after finding 1/4 17-18 on B Lap
making 2636.34 betw true E-W 4 line 7 and recet SET
mean SE 7 south would then be ~~2667.04~~ or 2633.52

9-16 dug 4' wide x 12' E+W on this E-W 4 line from well east
of center to west edge road found no stone verticul but some fair
sized limestones in apparent road fill + mush

9-28-70 ran N-S line between 7-8 (5) 16' east at C/M as
in place at SE 7 ran direct to NE 7 - this line came
18.91' east to nail RPed at E edge road or 2691 direct line.

over.

9-28-70 found by this line corner (4 on line) would be further west. dug again with tractor further west. well beyond any chance of corner being in place. Road evidently marked away. Will place corner on section line, which will move .36' west at C I M at S E 4 will move .72' west and intersection with E-W 1/4 line and 26.71 + .36 or 27.27 west of nail E edge road.

---

set by Michael Karrick 6-1854

12.42 Creek 10 lks wide runs SE

40.00 Set quarter section post

Burr Oak 6 N 18½ W 5 lks

" " 7 N 45 E 9 lks

48.00 Enter Barrens SW

7-18-1980 (1980 Remon BK) 1/16 South: Dug from the center of the N-S road West to the West edge of the road and in line with the fence East by 3' to 3½' to clay. Found nothing. Dug to cover total land between the section corner which came appx 12' West of ℄

1/4 Corner 7-8 Salem 106-15 #650806 (3)

7-21-1980 (1980 Remon Book) 1/4 Cor 7-8: Dug from East edge of hole dug in 1970 East to East edge of road. Condition good with 8" to 1' of black dirt on this side of road but found nothing. Also dug along South edge of 1970 hole in the center of the road but still found nothing.

7-25-1980 (1980 Remon Book) 1/4 Cor 7-8: Set 5/8" x 15" rod as the corner. We shot all the property corners in Sections 7 & 8 trying to determine whether this corner should be reset on the straight section line or East of line near the center of the N-S road. To reset the corner we used an average of the N-S 1/16 fence in the NE 1/4 Sec 7 and the N-S + E-W

1/16 fences in the SW 1/4 of Sec. 8. By setting the 1/16 corner West of 1/4 Cor 7-8 using the projection from the 1/16 West of Sec Cors 6-7-7-8 over the fence corner at the Center NE 1/4 Sec. 7 and then doubling the distance East, the 1/4 corner would have to be 15.8' East of line. By setting the 1/16 South of 1/4 Cor 7-8 by ~~projecting~~ doubling the measure from the calc 1/16 N of 1/4 Cor 8-17 (which corner is the N-S fence) over the N-S fence at the Cen. SW 1/4 Sec 8 and then projecting the line North would come 11.3 East of st. line

We split the difference between these two distances, extended the E-W 1/4 line Sec. 7 and set 1/4 Cor, Salem Twp is grading the road and they are going to put the road as close to line as possible. The new quarter corner is 4' So & rd. West and 3' West of center N-S rd. prior to grading. Set a 1/2" rod East of 1/4 corner on E-W 1/4 line Sec 7 extended and 60' East of 1/4 corner location RP's & CSD in PP# 8595 SW 42.59 and 1/2" rod East 60.00