/ 8-30-73 set 3/4" rod. M&L 2636183 #651304 (1)
6-28-78 CTC/P24

1/4 Corner 13-24. Salem 106-15.

5-1872 Hunter P200 no 209 S 24 H McCullough.

Corner gone. set corner M & L. 39.93 1/2. = 2635.71 S 89 1/4 E

Bearing of true line south N 1/2° E

6-1874 Hunter P255 no 255 S 24. Holdt. Anderson.

found stone center road. P 209.

- 1/16 south set stake M & L 20.00
BT 8" B Oak S 30 1/2 E 53 lks - 8" B Oak S 51° W 33 lks.

- 1/16 Center NW 1/4 24 set stake M & L 19.93 on E-W 1/16 line. 131538

(over)

4-1898 H Fraser P624 - No 566 S24 K Larson
E Erickson.

did not use corner -
- found 1/16 corner south. by B trees
drove stake and set large post as corner Witness

8-30-73 - Co. Survey

Set 3/4" rod by Midway & Line as per T. Hunter's Survey (1872)
Corner falls in Rock Cut area of County Road grading
and the Stone would be gone entirely Did not attempt
To dig for stones. - Meas. E & W 2636.83 E.T.C
R.P.'s - nail in S. side Cor. to post (new Cor. post) East - 46.25
℄ Co. Rd P.I. (½" pipe in place) - 12' E. of South - 79.9
Tangent line of ℄ Co. Rd from North - East - 12' ±
℄ Co. Rd on Curve (Rt ∠'s To ℄ Rd) W.N.W. - 31'

#C51304 (2)

1/4 Corner 13·24 Salem 106-15

Set by Michael Karrick 6·1854

43.35 Creek 40 lks wide runs NE

True 40.00 Set quarter section post

Burr oak 12 S 55 W 15 4

Dog trench

6-28-78 Set a CIC/25'p² at the location of the post set in 1973. The corner is 19.4 East of the center of Co. Rd 15 on curve and 10' West of 2 road North. The corner is 2' Se. of the fence East.

Should check this position in that Hunter road is 70' East Chain in Survey #209 which would move this corner

8 ft. 10' E to Center of Rd N
Run N-S ¼ line 24 and look for ¼ Cor 18-19 Rock.