/ 10-24-1973 set CIM over 5/8" rod down 16"
Corr 8-17-75

#051404 (1)

1/4 Corner 14-23 Salem 106-15
6-1874 Hunter P 254 No 254 S23 S Miles, Polo Nelson.
found stake standing and stamp SW BT. but atbo marked
plainly record of BT in error and moved place. stake N & E
several rods. on running line found stake in place nearly
on line and half rod west of half way. left as is.
- Meas east 40.02½. To corner found.
- 1/16 west set stake N&L 19.95½ To corner stake found
- 1/16 south set stake N&L 20.00. S1°E To stake set.

12-1894. St Fraser P562 No 516 S23 P Sorenson.
Nels Hanson
(over) Hatty

used corner fence post for line south this survey.
-1/16 south. set stake M & L. 19.97 To stone set.

4-1911 Chas Larson P154B S14. Faller, Knusel, Feigle
no mention of corner or 1/16 corners either east or west
Plat shows west 19.95 ± M & L
and east 20.01 M & L with 1/16 corner numbered
but not described or mentioned

10-24-73 found Taylor survey traverse nail by Calculations
set Corner 1.04 east - set C I M over short 5/8" rod in
bed rock. C I M below plow or 15" ± or about 16" ENE of
Corner post
Meas west 2631.65 south - 2625.85 east. 2636.9 ?

#651404 (2)

1/4 Corner 14-23 Salem 106-15

Set by Michael Karrick

40.00 Set quarter section pat

Burr Oak 15 N 50 E 74

" " 13 S 44 W 205