X 5-16-1977 Set CIM over pipe - pipe in Stake hole #651506

3½' deep - fd Perry's red cedar stake 0.8' left of pipe

¼ Corner 15-16 Salem 106-15

1-1870 Perry P90 no 134 S 16 N Jacobson.

set red cedar stake 4"x4" x 34"

-1/16 west set stone 6x9x20 likely N & E. to stone

set as center see 16. 9x9x21

6-1935 J Kerr B10 P5. Salem twsp.

dug for red cedar stake at E¼ 16. didn't find anything.

- meas east line 16 - 5269.3 from NE 16 a stone just N of cor post. to SE 16 a stone 1½' S corner post.

- set spad at 2634.5 for line west, staked road for grading.

Set by Michael Karrick 6-1854

32.15 Creek 20 lks wide runs East

40.00 set quarter section post in mound with trench pits charred stake and Orage Orange seeds N E & S.W.

10-30-1973 - Co. Surv. dug on dorble meas. over 1/16 Stone west, did not find Red Cedar stake.

5-16-1977 dug with backhoe on M & L pt. fd bottom 18"-20" of Red Cedar Stake (removed To office) set 1¼" x 3½' pipe in stake hole. Set 16" C I M over pipe. Corner 1' South of ℄, and 1.65' W and 1.65 No. of M & L point

R.P.s: Punch hole in E. end field culvert WSW 115.70
" " " W. " " " min " N. 32.66
" " " E " " " drive culvert NE 43.97
Concrete nail (red head) in So side cut off telephone pole unit bot WNW 89.13
NW corner telephone bot SW 98.2

+65°
SUNNY

11-18-99
EPA BB

82"651506" 1/4 15-16 106-15 SALEM
FOUND PK NAIL @ SURFACE 1' S & L CR 25
DUG DOWN 3" FOUND MINI PK CHECKED LOCAL TIES.
FOUND CIM DOWN 7" LOCAL TIES CHECKED
IN GOOD CONDITION. TIES TO CULVERT ENDS NORTH
ARE GONE. FIELD DRIVE NORTH IS GONE.