12-11-1975 CIA set

#651604

(1)

1/4 corner. 16-21 Salem 10 6-15

1-1870 Perry P90 no 134 S16. N Jacobson.
found orig stake in mound, pits plain.
set stone 6x13x32.
— 1/16 east set stone 10x10x29. no mags. Likely M&L.
— 1/16 west set red cedar stake 4x4x40 Likely M&L no mags

3-1895 W Fraser P618 no 561 S21 J. Saraland.
J Sillo
H Sillo
O. Stex
found corner set by Perry P90.
— 1/16 east found corner P90.
— 1/16 south ~~found~~ set stake M&L. 19.94. 131604 other

-1/64 south above 1/16 cor. set stake & stone M&L 9.97 658.02
-1/ center NE 1/4 21 set stake true intera lonee.
-1/16 1/64 south above 1/16. set stake M&L. 9.97. 658.02.
(Center NE 1/4).

12-11-1975 Found remaining 2' of 6" x 13" x 32" recorded stone. Dug out stone and set CIM over 1/2" x 18" rod with 16" (broken) piece from stone on N. side. Corner 5 1/2's of E-W fence and 2' East of fence N

RPs Nail E side of 18" Elm NNW 9.57
Nail N side (head) tree elm E 47.0
Nail S side 22" Elm SE 88.6
Nail E side 36" Box Elder S. 34.65

(2)

#165604

1/4 Corner 16-21 Salem 106-15

Set by Michael Karrick 6-1854

9.00 Creek 20 lks wide runs NE.

T.L. – 40.00 Set quarter section post, in brush erected mound with trench pits charred stake and Osage Orange seeds N.E. & S.W.

PT. Stg. 91+32.42

Co. Rd Align Pt. — ½" sq. rod.
44' East & 4' N. of Mc+B 1/16 Cor

Rd surface Stg. 5 Ely 6.5'
Top Cone 15' Cmpr SW, 8.1

Mc+B – 1/16 Cor. (5/8" Pipe w/cap) on w sh of Rd in N w edge of Curved driveway entrance – 6 ±o of Mailbox

12' W of ± Rd ± line main fence to EAST
30' S of [illegible] fence - West

4-21-92 County Surveyor Rd Crew down ± 1' ± snow lies in line of main fence north ± 5' south of E-W main line fence.

RP's 2SD in Newest C.P. to fence E-W N, NW & SS'
CSD in C.P. to lane fence running E ± S SSW 23.62'