#651605 (1)

/

section corner 16-17-20-21 Salem 106-15

1-1870 Perry P90 No 134 L16 N Jacobson

relocated section corner from 2 standing B trees and 2 B tree stumps set 4" square red cedar post.

– 1/16 east set 4x4x40 red cedar post M & L.

– 1/16 north set oak stake [marked.

5-1893 H Fraser P510 No 478 L. 17 Jacobson, Johnson Anderson, Town Board

found red cedar stake P90.

– 1/16 north could not find stake, set big stone M & L 19.98 1318.68

– 1/16 west meas 39.81 1/2 to 8x12x25 stone set M & L. (2627.8'

– 1/4 near center SE 1/4 17 set stone at 22.15 1/2 then 885 1/2 stake then 1462.23 584.43 8.85 1/2

Y-1911 C Larson P 160 B. L 17-20 Mrs Raffleson
found cedar post
Meas west 39.81 Meas south 39.82.

H-1933 J Kerr B 8 P 63 L 20
found cedar post

L-1891 Thos Fraser P 449 No 433 L 17-21
set iron stake N & L. SE 1/4 & E 1/2 17.

1-20-1968 Tankstone found remains of cedar stake drove iron marked conservation
30 D Sp in 30" elm W & W. 24.0 cut — tone pin driven into heart
30 D " " 36" elm. S W. 58.7 OK of old red cedar stake.
30 D " " 12" ash ESE 55.6 OK — also found 1/10 stone north (tipped
30 D " " 16" ash. SE 39.6 cut 1977 very near midway, in slight creek
1318.75 M & L 1977 corner now on E side of new corner post — iron thru cedar stake is a regular state conservation pin.

(2)

#45166

Section Corner 16-17-20-21 Salem 106-15

Set by Michael Karrick 6-1854

68.40 Creek 20 lks wide runs NE

80 00 Set post for corner to sections 16, 17, 20 & 21

Elm 20 S64W 35

" 18 N48W 30

" 17 N48E 49

" 10 S63E 68