X 8-27-69 set steel CM over CM set by Co Hwy Dept which was down 14"

1/4 corner 16-17 Salem 106-15 (1)
#651606

1-1870 Perry P90 No 134 L16 N. Jacobson.
set large stone as 1/4 corner.
1/16 south set oak post likely M & L no mrac
1/16 north " " " " " "
1/16 east " boulder 7x18x24 " " "

---

1-1891 Thos Fraser P449 No 433 L17-21
found boulder P90
1/16 south set iron stake M & L ~~0 761~~

---

5-1893 T F Fraser P510 No 478 L17 Nels Jacobson, B Johnson & Anderson & John Beard
found stone P90 No 134 (over)

1/16 south Coulds fnd stake - set big big stone 19.98 M.& L.
- west (point 5) set stone at 22.17 3/8 (1463.5) then stake at 8.87 8/9 (586.0)
then 8.87 8/9 (586.0) to center 17 a stone 5x13x20 inches line
- also set stake near center S E 1/4 south of point (5) 80 rods ±

---

6-1935 J Kerr. B10 Page 5 S 15-16-17 Town road
Mag Mile N & S. found stone Mag Mile 52 99.3
NE 17 - fence post - SE 17 cedar stake

---

12-1962 Co Hwy Dept. B 235 P39 B 276 8-27-69 found CIM
1/2" rod over limestone set by Co H D down 14"
Disc fence post S 22.05 — Disc P.P. N 31.4
NE corner basement S E 97.75 PP NW 47.58
set short CIM over stone flush with road surface

---

B276 P5 CHD 1962 - CIM 1964 found rod over limestone.

#651600 (2)

1/4 Corner 16-17 Salem 106-15
Set by Michael Kairick 6-1854
450 Creek 7 lks wide runs S W
21 70 Same runs SE and leave timber bears NW
40.00 set quarter section post in mound with trench pitts, charred stake and Osage Orange Seeds NE & SW

11-8-99
EPA 65

"651606" 1/4 COR 16-17 106-15 SALEM
FOUND CIM DOWN 3" IN BLACKTOP CR 25
IN Q IN GOOD CONDITION

11-22-99
EPA 66

1/16 E 1/4 COR 16-17 106-15 SALEM
FOUND IRON DOWN 0.3' + 1 1/2' S OF Q
CSAH 25 IN GOOD CONDITION. CORNER
FALLS 18' W Q CR 150 + IN LINE OF
FENCE NORTH.