#651609

See special card.
Found 1973

1/4 corner Center 16 Salem 106-15

1-1870 Perry P90 no 134 S16 N Jacobson.

set stone 9x9x21 on center likely intersections.

1/16 east set stone 6x9x20 N&L no mrks.

1/16 west set boulder stone 7x18x24 N&L no mrks

no mrks N&L boulder 11x23x28 north
stone 6x13x32 south

Later found 7 like two for east

(2) 1/16 corner between Center 16 and 1/4 15-16

- record stone 6 x 9 x 20 no mark either way 1-1870.
- set nail on line from nail at 1/4 15-16 to C1/4 at 1/4 16-17 3933.87 east of 1/4 16-17 1322.39 west of nail at 1/4 15-16.

11-1-13 found perfect position and ridge stone 5.7 S - 4.0 E. of nail or 3937.81 east of C1/4 1318.39 W of nail

Note the stone 2624.66 east of 1/16 stone found east of 1/4 16-17 which earns 1313.27 east of 1/4 16-17

- leaving Center 16 (found tipped out of place) of placed at 2626.42 to be 4316.45 west of the 1/16 found
- leaving the Mean of 1318.39 from 1/16 stone east to nail at 1/4 15-16 6.94 west of nail subject to direct measure and at least 7.6 south of nail at 1/4 15-16

See Card #5

① Pat's Corp Special Card
Pat between Center 16 and 1/4 15-16 Salem 10 6-15.
10-30-73 projected line carefully from 1/2" rod set at 1/4 14-15
over iron at Center 15 by Salem corner stone intersection
a meas EL 2613.39
- set nail at 1/4 15-16 on this projected line in line of poor
fence running north meas 2633.51 which came
some 6 or 7 feet north of center road.
R/to nail (should be up to 8' west 6' south) as key to future work.
39.35 N to staple of middle wire of fence on post
86.75 NW to corner nail on SW side Tele pole

there are no measurements west or east, so it is assumed
the 4 recorded stones west are on straight line and both
1/16 stones are N & S to center 16 and 1/4 corner in their
direction all 4 stones found and described

(over

(3) cont. RP to small iron set at mear over 1/16 stone (1/16 East of Cor.)
60.4 NW to old County disc on NE side PP S3.7
44.75 SW to old County disc on N side PP S3.4
corner 3' S of center E-W road, 3' E center road N
+this corner stone small enough top to be considered a perfect point. while Center 16 badly tilted and moved and 1/16 west big and hard to center accurately

---

Center 16 stone 1-1870 9x9x21 likely set intersince
1/4 corner south perfect corner (1/4 16-21)
1/4 corner north corner set (1/4 9-16) Cant be relied to reset anything.
set nail on line fence N & S and on random line described.
nail 2626.61 east of C/N at 1/4 16 17
" 1311.26 west of 1/16 stone found east (suspect to mear on line)
of center set at double 1313.21 or 2626.42 west of
1/4 16-17 then nail only .19 too far east and 3.8 too far North
for true Center 16. (over)

(17) RP random nail at Center 16. (stone found out of place now in north road edge.
49.53 S to 20" top of new cedar corner post
78.62 NW to staple on ground wire 1st staple below
no plate & PP # 8463

1/16 between Center 16 and 1/4 16-17 boulder 7x18x24
no mark any direction
set nail on random line on line fence north
13.2 ll east of C/M at 1/4 16-17
found unmarked huge boulder hard to center accurately
drove small iron centering as best as possible
1.1 east and 2.13 south of random nail
or 1313.21 east of C/M at 1/4 16-17
RP to random - see 3rd card used to record this line

(5) 3rd card of random line between ¼ 16-17 and east

RP to 1/16 iron between C1M ¼ 16-17 and Center 16 do not set

59.85 NW to ground iron NE side RP 8471 Road level

39.32 NNE to punch hole in west end field drive culvert

53.65 N to 20 D nail east side new cor post fence N

63.43 NE to Conc nail on NW side corner post

of fence running east from field drive.

If C1M at ¼ 16-17 and 1/16 stone east of Center 16 used this iron should go .18' due north to be on line

Changing fence below RP3