X 10-15-81 CIC #652004

1/4 corner 20-29 Salem 106-15 (1)

6-1905 JT Fraser P 92B 4 sections Salem town board

run line between 20-29. could not find corner

set nothing - total meas mile 80.04.

May have set stake but by note "found nothing, did not locate"

4-1933 J Kerr B 8 P 63 various woodlots.

found and used stake to run N-S 1/4 line origin unknown.

- meas east 2640
- " north 2636.8

5-31-1928 J Kerr B-2 P 39 found rotted stake still in place at new stake knotted on 4 sides with metal pail over both. meas east 2640 to holder & rod placed this survey.

Set by Michael Karrick 6-1854
west on true line
40.00 set quarter section post { Burr Oak 10 N 54 E 193
Black Oak 15 S 30 W 168

March, 1860 Samuel McDowell Bk. 64 No. 90 shows ¼ Post.
(See Survey for S.W. ¼ Sec. 20 & West ½ Sec. 29).

10-15-81 ¼ Cor 20-29 : Dug from Sanitation pipe and cap West 3½', South 9' 3" to fence line East and East 3½' to fence North.



Found a 10" x 9" x 12" boulder down 1'. Beneath the boulder there was a flat iron and short piece of pipe standing side-by-side. There were pieces of glass and crockery around the stone and around the flat iron and pipe. The pipe was filled with wood pieces and there appeared to be a stake mark on the North (cont.)

#652004

1/4 Corner 20-29 Salem 106-15 (2)

10-15-81 (Continued)

side of the flat iron and pipe. Set a CIC/p² on the corner. Put pieces of glass and crockery, the flat iron, and the pipe, along side the telepan. Set the boulder on the West side of the telepan. This corner 1' North of fence line ~~East~~ East and in line with the main line of fences N+S but 1' West of fence at corner. It is 1.8 NW of newer c.p to Fe N-S-E and 2½' NNW of an old c.p on the So. side of the Fe East. Drove a steel fence post on the North side of the CIC and put survey marker ~~sign~~ sign on the corner post. This corner is

7.9 South and 2.0 East of Sandstone pipe
RP. Spike in W. side 26" Red Oak NNW 37.85
10-16-81 1/16 East: 7d 1½" pipe up 1'.8 East of
Center of old C.P. to fence E-W-S.