X — 9-29-70 set C/M over orig iron bar found. #652005 (1)

section corner 19-20-29-30 Salem 10 6-15

11-1903 Ch Armstrong P68B S19. G. Aranby, Fred Lear.

found oak stake and iron bar 2' below road grade.

tied B tree plainly marked. 6" white oak N 56° E 48 links.

- meas west - found stone at 19.97 on 131.02 ac line also

stone at 39.89 - 2632.74 1/16 stake at 59.84 and town line corner

at 79.50 1/2 - 5247.33 making West 1/16. 19.67 record 19.73

and other 1/16 19.94 2/3 also 39.89 for S 1/4 19 very near correct.

- marking on plat 19.46 1/2 - 20.025 - 20.08 - 19.97 an error admitted

---

5-1894 & 6-1905 21 Fraser P92B 4 lectures Salem town board.

Quote - set stone according to Govt meas between SE 30 and 1/4 19-20

39.82 - also B.T. 6" bur Oak N 59 1/4 E 48 lks.

- meas N & S 39.82 - east 40.02 or 80.04. Etc

4-1933 J Kerr B 8- P 63.

: iron bar under 2 stones - 6" W oak - N56°E 48L. 31.68

may or may not have had and used corner.

no mons shown from corner -

9-22-70 Co Surv. run & meas line from W 19-30 each found stake set as 1/16 at 1299.45' R 1297.89 . 8' south of random line - found C/M set previously (same day) at 2617.25' R 2614.59 or 1317.8 between R. 1316.7. overrun 2.66' in 1/2 mile - cont line each set at 754.15, 1341.47, 1535.32, 2346.3 and 2645.71 — 9-29-70 dug with tractor found solid roadbed & huge limerock but found 1¼" x 12" iron bar with hook in top total 1/2 mile from C/M. 2635.56 R. 2632.74 overrun 2.82'. - corner came 3.3' from W edge road present surface 18' - " " 1.7' north of fence east (very little visible. - 16D in top new cedar corner post 1.7' S of E 34.17 - ½" rod in section line west top of high road north edge. as road curves back from south

see card # 2.

#GS2005 (2)

Card # 2 19-20-29-30 Salem

as the random line came only .12' north of C/M
as set one exact center rod found drove ½" rod
.11' south of rail on bank described 66.9' west of C/M
vertical angle between top transit To rod 17°54' 70.36'
- also referenced rod described
Orange knob cap on power pole NW side # 7598
S 50° 05' East to North 38.9'
chiseled on N side standard road



(over)

Set by Michael Karrick 6-1854

80.00 Set post for corner to sections 19, 20, 29 & 30

Burr Oak 8 N 13 W 187

" " 10 N 74 E 284

Dug trench

March, 1860 Samuel McDowell Pg. 64 No 90 shows Sec Cor

(See Survey for SW 1/4 Sec. 20 & West Half of Sec 29