X 9-23-70 set CIM over 5/8 x 16" rod org stone on N side

1/4 corner 19-20 Salem 106-15 #652006 (1)

6-1905 H Fraser P92B 4 sections 19-20-29-30 Salem Board

found stake marked 1/4 corner.

- corner used to set section corner 19-20-29-30 on a straight line south 39.82 for 1/2 mi. 2628.12.
(maybe ~~0~~ maybe not)

4-1933 J Kerr B8 P63 S20.

marked boulder found.

FOUND KERR'S MEASURE IN ERROR (1988) BOOK 8 PAGE 63

- meas east 2604.25 then 2622.0 to E 1/4 20.
- meas north 2629.75 to NW cor 20.

(OVER

9-23-70 Co surv. found sandy limestone 4½ x 9 x 24.
found or set by J Kerr 4-1933 field book no 8 page 63.
see Book 1, Page 10 - Kerr set stone
- corner location known by all local inhabitants.
- set C I M over 5/8" x 16" rod flush with surface. stones around top of C I M. 3/8" elec fence post west 1 corner.
- original stone set on N side C I M 4" below top. E I M 116.7
- railroad spike driven in P ± 8545 just south east slope near where spike enters pole. S end
- slope near to center road where road curves south E 245' ±
- northwest corner small house. ENE 131.0'
- center 18" white oak slightly east of N 17.4
- S E corner concrete patio slab. N 102.0

March, 1860 Samuel McDowell Fg 64 No. 90 Shows ¼ Post.
He Surveyed the S.W. ¼ of Sec. 20

#652006 (2)

1/4 Corner 19-20 Salem 106-15

Set by Michael Karrick 6-1854

24.30 Creek 18 lks wide runs S.E.

40.00 Set quarter section post

Black Oak 9 s 68½ W 75

White Oak 8 N 45 E 130