14/28192 Set CIC/Feldspar pipe 287-08 #652104 (1)

1/4 corner 21-28 Salem 10 6-15

3-1895 H Fraser ~~3-1895~~ P 618 No 561 L21 J Sandland J Sills, H Sills O Stein.

found mound with old stake in center just north of corner post set square boulder in place of old stake with new stake by side.

1/16 north set stake & boulder N 8° E 19.97 1318.02

6-1905 H Fraser P92B. L28-29-30 Town Board

found stone set P618.

meas west 40.02. to stone set this survey.

(over

5-28-28 J Kerr (B-2 1928) P38
random line N-S 1/4 line ⑤ 30' W of N 1/4 28 (not described)
line fell 20' W of S 1/4 (not described)
- set Center 28 8x10x26 at true intersections 2645.63 from E 1/4 28

6-16-72 found 1/16 stone & stake north - dug and probed entire area around corner post of fences E-W-N for 21 & 28 corner stone, found small dark spot north of corner post - set 3/8" ø fence post there and Z axed mear to 1/16 stone found mear. 1319.55 K 1318.02 Cont line north by traverse & elec mear to nail set 3-72 on mear from north and west. Computing would bring Center 21 north and .77 East of nail set., found center 21 stone .90 E and 2.3 W of nail. which should more 1/4 21-28 .71 North and .13 West after finding Center 21 stone at 1318.84.

(2)

#652104

1/4 Corner 21-28 Salem 106-15

Set by Michael Karrick 6-1854

40.00 Set quarter section post in mound with trench pits charred staked and Osage Orange Seeds NE & SW.

4/28/42 County Surveyor set LC/P² @ 3/8" for position set in (1972) where Co. Surveyor mark. Set sign post 0.8' north of monument. the corner is 1½ north of corner post to fences E-W-S; lies 1' East of Main line fence South