/ 6-16-72 set 1" x 4' rod at corner over stone found (1)
1/4 corner. Center 21 Salem 106-15.
1-1891 2has Fraser P 449 no 433 #652109
found stake with stone by side claimed set by Hunter.
-16 W set stake N & L

3-1895 2has Fraser 3-1895 P 618 no 561 S. 21.
J Sandland, J. Lillo, O. Sten.
found above corner P 449 which proved on E-W 1/4 line but 26 lks (17.16') west of direct N-S 1/4 line.
- removed and set stake and stone 3x8x24 inters lines.
-16 W found stake on line but too far west reset corner with stake and stone N & L 20.08 (1325.28'
-16 E set stake and stone N & L 20.00 (1320.00'
over

-16 N. set stake N 0 L. 19.94 (1316.04'
with "10" a prop corner N 0 L 9.97. (658.02' north
of center 21 a stake and stone. 1972 no corner but line (on N-S.

-16 S "2", set stake and boulder stone N 0 L. 19.97. (1318.02
with prop corner stake for line east north of above 1/16 cor.
toward center 21 5.47 chs 361.02' (can't read meas line E).
then 14.50 chs north 957.0' to stone 3x8x24
at center 21 (all 4, 1/4 corners are recorded stones in place.

3-13-72 found 1/64 stone north under fence 8" wide and chisel shaped with point up & small limestone pieces by stone, ground frozen mtn earth roughly R 658.02
to rd set on mtn from ℄ road at ¼ 20-21 - moved rail 2.8' east to make 00 rail 2644.96 ± from west. took R.P.s

(2)

Card # 2 Center 21 Salem 10 6-15

6-16-72 found 1/4 20-21 1.8 N and 1.5 E of .00 nail #652109
changing meas to nail at center to 26435 ±

- ran line with elec meas & traverse from assumed point at 1/4 21-28 over 1/16 stone found - from this computed corner should come 2.4 North and .77 east of nail.
- dug with tractor and found recorded size stone down 4.0' 2.3 north and .95 east of nail.
- of 1/16 stone found, nearly flying flat, west near correct then 1/4 20-21 conc mon not correctly placed. May search west & south for Fraser & Skeen stone

Note 6-19-72 found true corner at 1/4 20-21 over 8' west of Concrete mon found - removed Conc mon for 1/16 E line 1/4 21-22 over RPS Center

RPS to 1"x4' rod set as Center 21. over stone & misc junk.

60.35 SE to east nail holding number plate # 9124
to N side power pole.

43.15 N to 20D nail on E side 18" oak up 5'

76.25 SW ly to peak of large boulder setting vertically 3'± high likely 3'x4' base - meas to top of natural crack on E & W sides of stone running to peak of stone corner 3' North center traveled road.

- Meas S by electronic meter to 1/16 stone 1318.84 K 1316.02
- Meas W " " " to 1/16 east 1326.83 to 1/4 20-21 2653.66
- Meas E " " " to 1/16 east 1320.4 to 1/4 21-22 2640.8

"Center" now as set .09 North of direct line

R W M&L 20.08 1325.28 R E M&L 2000 1320.

Card # 3 Center 21 Salem 106-15 (3)

1/16 corner between Center 21 and 1/4 20-21 CIM 021 stone

6-15-72 dug with tractor found 7x11x19 boulder in hollow

road nearly flat with darker soil in area of stone

- set rod at best central area of stone found #652109

6-19 found true corner at 1/4 20-21

6-16 found true corner at Center 21

Meas entire mile by elec - 5294.47

found 1/4 20-21 at 2653.66 from center 21

- changed 1/16 rod E 1.22 N .56 so as to place

1/16 on true N & L 1326.83 to Center 21

Note Center 21 1"x4' rod has .09 N of direct line

2653.66 west to 1/4 20-21 2640.8 east to 1/4 21-22

pro-rated line and elec meas over RP W of Center 21

1/16 corner

RP to 1/16 west of Center 21 Salem (5/8" x 30" iron rod. (final)

43.2 SE ly to 7 up on W side PP # 7661.
57.8 NE ly to 20 D nail on E side 10" lightly blazed oak.
43.4 SW ly to center corner post of fence running south on west side driveway - this fence ± 3.5 W of corner re re-set.

Card #4 Center 21 Salem 10 6-15 #652109 (4)

1/16 corner between Center 21 and 1/4 21-22 C/M over stone

6-16 found true corner stone at Center 21

6-16 found above 1/16 stone large 4"x12" top down 4.5' with tele cable directly over stone, cable down 2.5' (1 pair cable marked and referenced ± center stone, temp corner

6-19 found true corner at 1/4 21-22 as recorded set C/M re-run and elec meas - found meas 2640.8 from Center 21 final and 1/4 21-22 C/M

6-20 reset 1/16 corner with 1/2"x24" rod .04' south and .2' east of temp corner above PB18 to make M&L 1320.4 / R 1320 of M Fraser 3-1895

Note 1"x4' rod at Center 21 .09 N of direct line 2653.66 meas to 1/4 20-21 2640.8 / east to 1/4 21-22 other RP 1.1 E of Center 21

RPs to 1/16 corner (½" x 2' rod) east of Center 21 Salem. final -

20.95 N To cone nail in small knot on W side PP # 7920

95.4 NEly to 20 D nail on SE side of 12" oak which lies ± 71' N of ℄ of traveled road

95 77

Corner lies 2' ± south of N edge traveled road.

7-25-77 Checked line for road grading. Found 1972 R.P.'s in place and out of construction area

4/28/92 County Surveyor fd ½" used 1" iron set in 1972 in good shape

1/16th S of center 21 Stone fd ½" iron set in 1972 are now gone in road construction.