1 #652505 (1)

section corner 25-26-35-36 Salem 106-15

5-1873 Hunter P220 no 224 L36 W. Lee, L Haskins
Peter Anderson.
found stake in center road
accepted by surrounding land owners as corner.
1/16 east set perm stake M & L 20.01 1/2 N 89 3/4 W
1/16 south set temp stake M & L 20.02 N 10' E
1/16 center NW 1/4 36 set stake at inters lines.

5-1873 Hunter P222 no 225 L25 A Holt, E Dwyn, H Hanson
McDonnald.
found short stake center road P220.
1/16 north set stake marked M & L 19.94 6" Oak S41 3/4 E 46 lks.

6-1887 Hunter P420 no 409 L26 Alis Starkson
found stake driven even with surface in line of (over)

old fence running east and undisputed corner.

11-3-69 road deep fill and black topped, county hwy dept. did not search or set any corner.

Meas south one mile - record 20.02 M & L with entire line very near straight - record says one half mile 2 links shorter, no mention of which one.
- found E-W fence at 2638.3 a recorded stone now 10' fill and blacktop. - found nail in black top cented set by county at 5279± accepted as corner for use in line east.
this section corner hopelessly lost, could meas east.

1960 B 242 P6. set 60D spike.
RP Disc cor fence post W. 54.35 - Hub F West 65.18
Hub SW 75.16 Hub SE 74.85
Meas S 5278.80

(2)

#652505

Section Corner 25-26-35-36 Salem 106-15

Set by Michael Karrick 6 1854


80.00 Set post for corner to sections 25, 26, 35 & 36. Erected mound with trench pits charred stake and Osage Orange seeds NE & SW

11/1/78 Dug from 1½' East of the traverse nail, set in line with the fence West and 4½' W of ℄, East for 3½', North for 3½', and South for 3½'. Found 6' of fill over 4" of black dirt on clay. Found nothing. A large concrete culvert lies just 14' North of the t.n. Conditions not good.

7-8-1980 (1980 Remon BK) 1/16 North: Dug with backhoe from t.n. set on line from 1/4 Cor 25-26 to t.n. @ Sec. Cor 25-26-35-36 and in line with the fence East for 3' North, 2' South, and 4' East (meas. at bottom of hole) found a 6"x8" topped boulder appx 18" long & dug well down into clay and with a good stake hole on the NE side. Top of boulder down 7½'. Drove 5/8" smooth iron in the stake hole. Stake appx 3.2 East and 1.65 South of the t.n There was a ½" iron @ the road surface appx 2.2 East of the t.n. We removed the iron to dig-

stake { 9.55 W / 7.07 S t.n. { 6.13 W / 8.97 S ½" iron { 8.33 W / 8.62 S

7-7-1980 (1980 Remon. BK) Sec. Cor. 25-26-35-36: Dug from a point 6' East of the t.n., East for 6', North 3', and South 4' as follows:



by 7' deep to clay. A large concrete culvert has been dug in across the North End of the hole beginning appx 1' North of the t.n. Found nothing.

Section Corner 25-26-35-36 SALEM 106-15 (3)
#652505

7-9-1980 (1980 Remon BK) Sec. Cor 25-26-35-36: Dug out remaining strip of road between hole dug 11-1-78 and hole dug 7-9-80. Found nothing.

8-13-1980 (1980 Remon BK) Sec. Cor 25-26-35-36 This corner set E-W at double the measure from Sec. Cor 26-27-34-35 over the N-S 1/4 line of Sec 26 (N 1/4 Cor was Center) and N-S at Hunter prorated measure from 1/4 Cor 25-26 (prorated against Hunter measure on the E-W 1/4 line of Sec 26.) Set CIM on 1/2" x 18" rod.

RP's: Punch mark in conc. culvert WNW 27.87
Punch mark in conc. culvert ENE 16.48

The corner is ± 2' North of the fence West and 5' East of the ℄ Co. Rd #15

6-27-96 - RESET CORNER WITH P.K. NAIL FROM 1995 TRAVERSE INFO.
SET REF PIPE WEST OF CORNER 3' SOUTH OF FENCE WEST.
TI@ REF PIPE
ART P.K. IN PP #47558 NNE OF CORNER. NEAR BROWN HOUSE WITH DECK
TO SEC. COR. 77° 52' 12"
TO SEC COR HOR 63.04
C.H.D. DISK IN COR FE POST W.S.W. 61.41

10-24-96 CHD SET 1" SA PIPE W/CAP