#652509

/

1/4 corner center 25 Salem 106-15

5-1873 Hunter P22~ no 224 S36 21m Dec

L Hackins, Peter Anderson

set stake at intersa lines from all 1/4 corners

1/16 south set stake N&L 19.90 } N 1/4° W

1/16 north set stake N&L 19.96 }

bearing of E-W 1/4 line S 89° 25 E