\ # 1 10-16-90 set ½" rod over 1¼" pipe and org stone 8' deep ①
6-30-72 set C/M over pipe found & checked #652705
section corner 27-28-33-34 Salem 106-15

No records

5-28-28 J Kerr B-2 P37 L 28
found limestone on N side road. 4"x4" top with high ridge in center.
- meas line betw L 28 & L 33 5281.7.

---

6-7-32 J Kerr. B 8 P14 L 34 Pet Lee.
found stone, run line south 5260' to S W cor 34 limestone
- 1/16 south set iron M & L 1315.0'
- 1/16 east set iron M & L 1320.27
- 1/16 center NW ¼ 34 set iron 1319.0' from W - 1316.8 from north.

(over)

1935 J Kerr B9 P6. NE¼ S33. Gilbert Olson

found stone -
found 1/16 south iron bar 1315.0
- 1/16 west set stone with notch in top (22.3 S of F cor).
at 1320.4 M & L. or 1320.4 west of L Stone NE33.
- set iron at SW cor of 40 acres (NE¼ of NE¼. Sec 33).

---

10-5-70 Co surv. Corner if any dep in the road intersection.
set nail 5284' west of 120 D at 26-27-34-35. in outer traveled surface E-W-S roads - road dep fill with N-S culvert west 20'+
- Meas from area S 33-34 checking 1/16 fence post south of 28-28-33-34
- found nail to be. 5268.4 indicating nail 8'± too far north.
- Meas from east & line from north at ¼ 27-34 indicates stone moved be. 4'± east of nail - RP orng nail - hole in S end road culv. SW 28.18
- Center N end road Culv - yellow mark. NW 25.4
dig 4' E 8' S.

#2 Card # 2 27-28-33-34 #652705 (2)

10-16-70 dug over 8' deep found logs, huge 4' round stone & 3' of rock fill before coming to clean black soil, found 4"x4" top limestone as recorded by J Kerr 5-1928

B-2 P37 dug on 10-13 for 1/16 mile and 1/4 28-33 found nothing then after finding above found 1/4 28-33 easily

- Corner came .78' south of line from SE 27 over stone Set by J Kerr 6-1932 B 8 P 14. M&L 2640.55
- came .5' east of 5284 nail or 2639.7 which when SE 27 moved .6 east (Top stone before straightening up) was 2639.7 from S 1/4 27 east also.
- came 5261.08 north of L stone at S 33-34 Salem
- came 2638.78 east of 1/4 28-33 (boulder found 10-20-70 slightly out of plumb so set exactly M&L (over 1/16 W.

1/16 west 10-13-70 dug for stone recorded found 9-1933
B9 P6 J Kerr at 1320.4 west of 27-28-33-34. found
nothing - mear south to heavy 2"+ manure spreader axle cor
post altered as 1/16 corner set 13'15' south of stone, proved corner
gone. - set 1/8" x 13½" thin wall pipe as 1/16 at M & L 1319.39.
R 1320.4
Came in center road, exact line fence south
38.25 south to huge cor post.

topo of fence running east south of cor. about 1317.8 ± R 1315.0
RP to rod set over long 1¼ pipe with cinder block pieces & track
- long hard cone nail in top new elec cor post 6" dia with iron brace to posts east and southwesterly [gone 9-1976] ESE 106.9
- Tap cap in base NE end PP # 7424 NW 69.5
- hole in S end road culv center [gone - Sept. 1976 Cut + Bolles - road regraded] SW 26.31
- punch mark N end " " NW 28.45
- eyeball line RP power pole E side to main pole line S came W 28.3
- Corner 5' S of E-W road. - 5' N of S road. 6-30-72 set C/M

#652705 (3)

Section Corner 27-28-33-34 Salem 106-15

Set by Michael Kerrick 6-1854

80.00 Set post for corner to sections 27, 28, 33 & 34 erected mound with trench pits charred stake and Osage Orange seeds at each angle

---

11/14/92 VINCE FANGMAN TOOK R/Ps

37.90 to SW END 18" CMP SW

31.64 TO NE END 18" CMP NW

69.50 TO SPIKE & B.C. IN P.P. NW