X 7-15-68 set C I M over stone found. (1)

#652909

¼ Corner Center 27 Salem 106-15

3-1878 Hunter P 331 No 325 S 27 C Johnson & others

set stone 8 x 10 x 23 at true intersection lines

-16 N set stake N 4 L 20.06½ (1324.29 to boulder

8 x 10 x 18 set in place of orig stake found.

-16 W set stake N 4 L 19.96½ (1317.7 to marked

stake found in N-S fence by fence post.

-16 S set boulder 8 x 12 x 23 N 4 L 19.92½ (1315.05

to stake found with witness hole filled with sand

where 2 boulders set vertically

over

-16 E. set boulder 4½ x 9 x 28 M&L 20.09. (1325.44
to 2 boulders set vertically in place of stake found.
- 16 stakes set at interse lines in NE and SE ¼ & of
section 27.

mozelly
County Hwy Dept. all data below B76 P3 Hank Kalb.
6-17-33 found stone mon sta 105 + 35.6
Δ R 90°14' D 290 T 200.5 L 311.14
36.7 SE to tele pole - 36.0 NE to tele pole.

3-16-34 a Quote exact Stone removed by unknown party.
found old stake about .6 below surface and .3
east of point where stone should be.
36.6 SE to tele pole - 40.95 SW to tele pole.

See card 2.

Card # 2 Center 27 Salem 106-15. (2)
addition caption B 76 P 3 Co H D H Kalb.
#652709
28.6 x m Mdwl. Calv NW Calv always SW
68.0 Hub SE in fence stone.

Station actual ¼ 27-28 130 + 80.3 Δ R 0°13' going W.
Station actual ¼ 22-27 78 + 93.3 Δ R 0°07' going S
both stone monuments: R2635.4 R 2648.58
actual mean figured W 26346 N 26423

over

7-15-68 J Kerr set C/M over top stone as found below iron riser found

58.99 NE to ½" rod by Co Hub 212 found.

33.86 SE to cross in center conc Curb / Hwy Center.

26.35 SW same west end above east end.

---

10-6-70

63.5 NE to new R.P. in new trans Pole. (disc) ran transit aerial from P.O.T. 1289.53 S of center C/M and County nail at ¼ 22-27 also nail at 2625.6 on same line

---

10-15-70 found 7/16 stone easily R 8 x 12 x 23 (1315.05 about 8 x 10 x 18 shows top broken off some. No doubt of genuiness of stone. This came 4.5 West of center road.

See card # 3.

line as run fell 2.38 east of stone, set pipe (3)
riser over center stone and dash weight west
side of stone with track RPs to 1/16 #652709
26.7 W to N-S road fence west of road.
40.4 NW to nail in crotch small cherry tree
42.5 S.W to center 2" elm tree.
145 N to eye center field drive east into field

this line fell 3.0 east of sand hole at 1/4 27-34
and 3.25 east of J Kerr stone set M & L in 1932.
J Kerr stone came 2626.1 S of center 27 C 1/4.
Hunter sand hole came at 2629.9
No corner set at 1/4 27-34 - both referenced to something
in place. above or below. JK S of 1/16 1311.2 Hunter sand hole
1315.0

6-22-72. dug with tractor on west side of C/M. 6' deep, 3' N and S of C/M. found long boulder with county hub rises and limestone below boulder about 8 x 10 x 18. a little short of 8 x 10 x 23. Corner appears to be genuine as recorded County claiming stone gone must be some other area. Lift old parts be found accepting Corner as found Card 4 indicates center could be 2.23 east as when 1/16 east found at 1327.8 while 1/16 E 1325.57 (elect) R 1325.94 Hunters mean south near exact, also 1/16 E to 1/4 26-27 - Center to go east 2.23 would really foul up line south i.e. - Hunters 1/16 stone south and east hole would indicate center should go west about 1.8

Card # 3. Center 27. Salem 106-15 (4)

8-15-73 ran electronic line direct between C/M S at Center 27 and 1/4 26-27. set 120 nail in line fence North and south at 1/16 corner. #052709

- dug by hand, easily found 16" ± of 4½ x 9 x 28 stone set by Hunter 3-1878 M & L 26.09 1325.94

- found stone at 1325.51 from east 1327.8 to west indicating still possibility Co Hwy Dept did not reset stone properly in 1934

- 1/16 stone only. 2 south of direct line, 2.23 longer W-½

RP S¼ east. 23.4 3' W & N to Cone nail on bottle cap in west side RP # 7738.

45.0 S to 20 E ado 20" cherry low in root brace