10-20-70 set ½" rod over 1"ø x 3½" pipe over 2' deep
6-30-92 set CIM over pipe found below. #652804 2

¼ corner 28-33 Salem 106-15

No records -

12-1939 J Kerr P556B L28 B 17 P18&19 C Paulson

re run line from corners found 5-1928 B-2, P 37.

set limestone M & L 2640.84 - not stated as set by assumed set. not mentioned as found?

1/16 east B9 P6 ~~set~~ found stone with notch in top 22.3 S of Fcor.

no info as to whether what lines were run. 1320.4 E to Sec Cor

B76 back corner. found boulder 6" below surface.

RPs Oak tree SE 37.3. uncertain information ??

Oak stump NE 35.0

OVER.

5-1928 J Kerr B-2 1928 P38. set Center 28. intersections
ran N-S 1/4 line S 28 used both N 1/4 and S 1/4 no dist.

12-1939. J Kerr B 17 P 19.
staked 20 acres with SW cor tract as SW cor 28.
NW corner tract as 1/16 cor M & L 1315.85 with iron 33' east
NE cor " 660.5 east of 1/16 cor 89°47' south to east
SE cor " 660.71 east of SW 28 90°02' north to east
angle at 1/4 28-29 south to east 89°36'
— south line 28 shown 1320.42 4 times but not run.

10-5-70 Co surv. set nail in line of fence south
7918.0 from 120 D at 26-27-34-35 set 1967 from north.
10-6 - near SW 28 to nail 2643.07. R J Kerr 2640.42
— no evidence this corner on line but near of Mile
5-1928 B-2 P37 showed 5281.7 which is 2640.85
— 16 east set nail in line fence south 6608 from 120 D E
or 1314 from nail at 1/4 28-33

Card # 2 1/4 28-33 Salem #652804 106-15 (2)

10-13-70 Meas from corner part of 40 acres surveyed out for Gilbert Olson 5-1933 B9 P6 a large solid steel axle of old spreader placed in cement claimed by son of Olson as spot wher I Kehr set corner Meas 1315 ft recorded dug extensively with tractor to clay. very little of old road left. Corner gone & in that area which would be very near center road. - pushed line West from nail set at 5260 from south W cor 34. which came close to 1315 from fence E & W S/4 27-28-33-34 over area at 1/6, line came 5' north of nail set at 1/4 28-33. dug 4' wide over 5' deep & probed 4'in all directions deep black soil as old road bed over 3' down corner should be there - will reproduce line from SW 28 at angle given B17 P19 when notes of this survey given P559 say all corners of SW 1/4 28 were found in place

10-20-70 Co surv - dug again with tractor on true line between section corners and midway 2638.8, found stone boulder with dented notch in top approx size 8x10x18 exact upright position in doubt as stone slightly tilted very close, within tenth of M & L so placed exactly M & L - set 1"x 3½' pipe below C/M line - set only ½" rod until land scales - witness stone N 0.8' - corner slightly south center road and 4' west of fence south RP hard nail on east side corner post of fence 4' E of L 33.77 south and west and east " " 75.0

— ½" x 30" galv pipe under wire fence up 3" 6-30-72 top center 5th steel fence post W of true SW 78.36

— 5/16 set dug extensively in line fence south, also mean 13.5 ea recorded prior corner post at center NE¼ 33 found northing - set 7/8"x13½" thin steel pipe midway 1319.4 (mon 1320.42) - corner exact line fence south - corner 38.25 south and on center road

6-30-72 found iron set C/M iron pipe found below and additional RP

#1652804 (3)

1/4 Corner 28-33 Salem 106-15

Set by Michael Karrick 6-1854

40.00 Set quarter section post no suitable trees for bearings near, therefore erected mound with trench, pits, charred stake and Osage Orange Seeds NE & SW