#652904

1/4 Corner 29-32 Salem 106-15

set by Michael Karrick 6-1854

40.00 Set quarter section post Tree line

Burr Oak 10 N47E 133

" " 9 S27W 105

11/9/78 McAthie set a pipe and cap M+L. The corner is on ℄ E-W road and 6' West of the corner post to the fence North.

March, 1866 Surveyed Mc Donell Pg 64 No. 70 Show - 1/4 Post

See Survey for West 1/2 of Sec 29.

T=60
P=28.9

5-25-99
MW RF MC

652904 b 1/4 Cor 29-32 106-15 Salem

Set Ref pipe w/Cor 41' North of ℄ CR 17

TQ Ref pipe BS 0°00'00"

&Rt P.K. in East face P.P.# 45227 (2nd pole West on North side CR 17

to 1/4 Cor 29-32

192° 16' 40"	193° 09' 52"
0° 02' 06"	0° 55' 24"
T 192° 14' 34"	192° 14' 28"

To 1/4 Cor 29-32

VA 90° 28' 22"

slope 177.53 Hor 177.52

To PK 176.29' West of 1/4 Cor 29-32

&Rt 273° 50' 22" VA 85° 43' 50"

slope 41.00 Hor 40.88

To PK Nail 231' east of 1/4 Cor 29-32

&Rt 84° 43' 42" VA 91° 42' 14"

Slope 406.10 Hor 405.92

T=60
P=28.9

5-25-99
MW RF MC

652904 1/4 Cor 29-32 106-15 Salem

Set Ref pipe W Cor 41' North of ℄ CR 17

TQ Ref pipe BS 0°00'00"
ART P.K. in East Face P.P.# 45227
(2nd pole West on North side CR 17
to 1/4 Cor 29-32

192° 16' 40" 193° 09' 52"
0° 02' 06" 0° 55' 24"
192° 14' 34" 192° 14' 28"

To 1/4 Cor 29-32
VA 90° 28' 22"
slope 177.53 Hor 177.52

To PK 176.29' West of 1/4 Cor 29-32
ART 273° 50' 22" VA 85° 43' 50"
slope 41.00 Hor 40.88

To PK Nail 231' east of 1/4 Cor 29-32
ART 184° 43' 42" VA 91° 42' 14"
Slope 406.10 Hor 405.92

6-30-99 Remove 4" broken off piece of pipe

At P.K 176.29 west of ¼ Cor 29-32
To P.K nail 549.68 East of S.W. 29
VA 89°52'50"
Slope 1912.60 Hor 1912.595

To P.K nail @ 1/16th Cor & prop Cor
VA 89°53'02"
Slope 1143.06 Hor 1143.06

To Fd Pipe @ Prop Cor 660' W of 29-32
VA 90°17'18"
Slope 483.88 Hor 483.88

To ¼ Cor 29-32
VA 91°40'34"
Slope 176.30 Hor 176.23

Art PK in P.P. # 45227 to PK
549.68 East of SW Cor 29

353°45'46"	354°11'30"
0°00'32"	0°26'24"
352°45'14"	353°45'06"

"65290H" 1/4 COR 29-32 106-15 SALEM
SURVEY CREW SET PK NAIL AT SURFACE
FROM TIES.

10-20-99
EPA MC