/ 9-30-70 set C/M over Ford T axle org stone
½ N side ½ S side stone also on E side

1/4 corner W 1/4 30 #653006 Salem 106-15
E 1/4 25 Cassteo 106-16 D.C.

5-1894 2# Fraser P92B 6 sections 5-1894 & 6-1905
this corner set. 5-1894 Salem town board.
- found stone planted as corner? (Quote)
- Meas north 39.87½ (2631.75

9-1970 Co Surv found large solid steel shaft as corner.
- no dodge Co. surveyor or any local surveyor knew of this corner.
- will dig in area with tractor, land level no chard stone gone.

9-30-70 shaft proved to be short cast sash weight.
dug with tractor found below ~~Sash~~ weight with limestone
5 x 8 x 32 in clean black soil

OVER)

stone to long to bury - broke in half - placed 1/2 on N side
1/2 on S side also slim stone sliver 3x7x18 ± on E side.
- set full length Model T axle below C in M glass etc.
- corner lines fence east & old fence in massive tree line W
- 40 D in hub on N side of easterly of two massive oaks
near 24" - this trees have siamese limb connecting them
abmt 8' up E & W - very unique growth. 5' N & W 88.5
- coke cap on SW side PP 3803 SE 54.4
- hard nail on S side new 8" cross cor post E 33.02
- corner in center road in line fence east.

Set by John Ball 10-1854
15.02 Black Oak 15 inches in diameter
40.00 set post for quarter section corner
Burr Oak 16 S 45° E 191 links
Burr Oak 12 N 81° E 244 "

11-15-85 L.C. Sa CIP
gone. Set 1½" x 12" pipe
½ below surface in
± mound tile
Tree to C.P. East also
gone.