9-21-81 Set CIM.

#653104

1/4 Corner South 1/4 31 Salem 106-15
North 1/4 6 Rock Dell 105-15

Set by John Ball 10-1853
40.00 Set post and drove charred stake for quarter section corner, Built mound with trench per instructions Planted SE Osage Orange NE Apple Seed.

9-18-81 S 1/4 Cr 31: Dug from the transit nail set in the ℄ E-W road and in line fence N & S; West 3', East 5', South 1', North 4' by 6' deep to clay. Fill all the way to clay. Found nothing

TN { So 8.48 / W 7.78

9-21-81 1/16 West: Dug in line with the fence North (fence North point came 4' to 5' West of the t.n) and in the center of the E-W road. The area appeared to have been cut down into bedrock. There were huge pieces of limerock mixed into sand subsoil over more bedrock. There was no black dirt at all

9-21-81 S. 1/4 Cor. 31: Set a CIM over a 1/2" x 18" re-rod on line between the section corners and at prorated Govt measure. Corner in ℄ E-W road and 2 1/2' West of fence N ∓ S

RP.'s: CSD SE side pp # X776 NE 39.84

CSD SW side pp # 95 (middle pole of 3 large poles) NW 80.96

CSD West side RR the corner post to fence South SSE 44.55