9-28-81 Set CIM

#653106

1/4 corner West 1/4 Set Iron 106.15
East 1/4 36 Canceled 108.16 Dr County

No records in court house, found unrecorded County corner and found no 1/0 limestone 13.9.5 north of hwy corner which came in exact line fence east & west - Cont mean north double on 2639.0 - line over 1/0 stone would bring corner nearly off road on west side - direct line betw C/M's came 4.46 east at 1/0 stone - 10 2'-7" dug with Caterpillar (Forest Service) for 1/4 cor after finding 1/0 by same method - road on slope north from high crest corner 190' south over - dug entire road with cat found road worn away

– found nothing – road bed gravel with stones interspersed
R Pcd nail set at 2639.0 on direct line RPs may be gone
Corner would have to be remade & re-aligned

Hills 1/16 south, no fence in place.

Nail in N side cherry tree in fence line E. 84.56

– 7/8 x 13" steel stake on transit line from head of
Nail in cherry tree, south side (NE pc 2'±) W 7.00

– corner in exact line fence E & W, 4.46 N of direct line

Set by John Ball 10-1853
40.00 set post and drove charred stake for quarter section corner
Built mound with trench per instructions Planted Osage
Orange SE NE Apple seed.

9-28-81 W. 1/4 31: Set a CIM over a 1/2" x 18" rerod at double the line and measure from SW 31 over the 1/16 N 1 rod on stone Fd 9-18-81 corner 9' West & N-S road and 190' N & fieldmins E & W on top of small hill south of corner.