#653305 (1)

section corner south 32-33 Salem 106-15
north 4-5 Rock Dell 105-15

No records -
Co Hwy Dept finds wood stake - Metal corner in place

Disc	power pole	NW	46.95
"	"	NE	44.8
"	tele pole	SE	48.0 or 49.0
"	"	SW	57.75

1935 Co H D B75 P74. - state on 2 sides.
found NE cor 4 meas west 2633.6 found boulder. doubled meas.
with true line set spike a corner. Tele P #495 NE 53.4
" " #496 SE 59.2

(over)

Meas north found boulder NE cor 32 5274.9
Meas west 5293.0

B 79 P 19. Co H D wood stake 1935 Sta 347 + 64.2
1946 Ties Hub NW 83.6 - Lp PP NE 44.8
set rod in 1946 Lp Dec tele P SW 57.75 - Lp TP SE Dec 48.0

1966 Co H D B 303 P 41
Lp D P P NW 46.99 - Lp + D brace PP NE 44.41
D Lp cor FP SE 48.49
Sta 461 + 73.68 at Δ 0° 13' Lt going N.
5274.12 North to 28-29-32-33

10-22-70 Co surv found recorded boulder east 2633.78 (9 + bcor 5 & 33
then 2633.37 to limestone at S 33-34

1929. Co H.D B 66 P 18 set point by line + meas from
east over 1/4 corner. 2633.9
tele P NE. 54.0 tele P SE 39.0

#653305 (2)

Section Corner South 32-33 Salem 106-15
North 4-5 Rock Dell 105-15

Set by John Ball 10-1853

80.00 Set post and drove charred stake Corner to Sec 4, 5, 32 and 33. Built mound with trench per instructions Planted SE. Osage Orange NE Apple seed.

6-25-1980 (1980 Remon BK) N 4-5 : Dug centered over nail found in center of intersection and used as traverse point. Found nail over 3/8" x 21" pipe inside a 3/4" x 32" pipe driven into a 2" diameter stake (sharpened) driven in a road appx 2½' deep

nail { W 8.32 / S 8.29 } 3/4" pipe { W 8.29 / S 8.31 } stake { W 8.28 / S 8.28 } Three

had been no digging beneath this road and the last road was 5' deep and it was 7' to clay. Found nothing further.

9-21-1981 S. 32-33: Set a 5/8" rod at location we removed spike to dig in 1980 from local R.Ps.